GOVERNMENT O F ANDHRA PRADESH

ABSTRACT

RWS&S – Chittoor - Dilapidated OHSRs – taking up of certain repairs and protection works to OHSRs and other components to single village scheme (SVS) in Chittor district for 675 works With an estimated cost of Rs.19.63 Crores (Rs.13.93 Crores for Kuppam Constituency and remaining Rs.6.00 Crores for other 9 constituencies) under SDS grant 2018-19 - Administrative sanction - Accorded – Orders – Issued.

PANCHAYAT RAJ AND RURAL DEVELOPMENT (RWS.II) DEPARTMENT

G.O.Rt.No.882 **Dt:06.07.2018**

Read the following:-

From the Chief Engineer-IV, RWS &S, Lr.No.AE (B) / CE_IV/CTR/ / SDP /2018, Dt.01.06.2018.

******

ORDER:

In the reference read above, the Chief Engineer-IV, RWS &S has requested to accord administrative sanction for taking up of certain repairs and protection works to OHSRs and other components to single village scheme (SVS) in Chittoor district for 675 works with an estimated cost of Rs.19.63 Crores (Rs 13.93 Crores for Kuppam Constituency and remaining Rs.6.00 Crores for other 9 constituencies).

2. In the circumstances reported by the Chief Engineer-IV, RWS &S, A.P., Vijayawada, Government after careful examination of the proposal hereby accord administrative sanction to the Engineer-in-Chief, RWS &S, A.P, Vijayawada for taking up of certain repairs and protection works to OHSRs and other components to single village scheme (SVS) in Chittor district for 675 works with an estimated cost of Rs.19.63 Crores (Rs 13.93 Crores for Kuppam Constituency and remaining Rs.6.00 Crores for other 9 constituencies) under SDS grant 2018- 19, with a condition the actual expenditure under the said grant is within the budget allocation during the financial year 2018-19.

3. The Engineer-in-Chief, RWS &S, A.P, Vijayawada is therefore requested to make the entire State and sub –allocation category wise also make at his level as per the demand and need. The Department is taking all precautions to justify the demand of needy districts.

4. The Engineer-in-Chief, RWS &S, A.P, Vijayawada shall take further necessary action in the matter.

5. This order issues with the concurrence of Finance Department vide their U.O.No.46023/2/FMU.PR & RD, RWS/2018, Computer No. 514112, Dt.28.06.2018..

6. A copy of this order is available on the Internet can be accessed at www.ap.gov.in/goir.ap.gov.in.

(BY ORDER AND IN THE NAME OF THE GOVERNOR OF ANDHRA PRADESH)

B.RAMANJANEYULU
SECRETARY TO GOVERNMENT

To
The Chief Engineer-IV, RWS &S , AP, Vijayawada.
The Engineer-in-Chief, RWS &S, A.P, Vijayawada.

Copy to :
The OSD to Minister (PR, RD & IT E &C)
The P.S to Secretary to Government (RWS)
The District Collector, Chittoor District.
The Superintending Engineer, RWS & S, Chittoor District.
Sf/Sc.

//FORWARDED BY ORDER//

SECTION OFFICER
(PTO for Annexure)

ANNEXURE TO G.O.Rt.No. **882**, PR &RD (RWS.II) DEPARTMENT, Dt. **06.07.2018**

PROPOSALS FOR REPAIRS AND RENOVATION OF DILAPIDATED OHSR's

DISTRICT : CHITTOOR

Sl No	Constituency	Mandal	Gram Panchayat	Habitation	Type of Structure OHSR/ELSR	Capacity (in KL only)	Nature of Damages and present condition	Est.Cost (Rs. In Lakhs)
1	2	3	4	5	6	7	9	10
1	KUPPAM	GUDUPALLI	AGARAM	AGARAM	OHSR	20	Top slab, verticals and Valves damaged	2.00
2	KUPPAM	GUDUPALLI	AGARAM	JABBIGANIPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
3	KUPPAM	GUDUPALLI	AGARAM	JOGINDLU	OHSR	20	Top slab, verticals and Valves damaged	2.00
4	KUPPAM	GUDUPALLI	AGARAM	KOTHAPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
5	KUPPAM	GUDUPALLI	AGARAM	THODELUGATTU	OHSR	20	Top slab, verticals and Valves damaged	2.00
6	KUPPAM	GUDUPALLI	BEGGILLIPALLI	BANDAKOTHUR	OHSR	20	Top slab, verticals and Valves damaged	2.00
7	KUPPAM	GUDUPALLI	BEGGILLIPALLI	GOKARLAPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
8	KUPPAM	GUDUPALLI	BEGGILLIPALLI	NALAGAMPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
9	KUPPAM	GUDUPALLI	CHEEKATIPALLE	CHEEKATIPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
10	KUPPAM	GUDUPALLI	CHEEKATIPALLE	PACHARLAPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
11	KUPPAM	GUDUPALLI	CHEEKATIPALLE	VENGEPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
12	KUPPAM	GUDUPALLI	CHEEKATIPALLE	VENKATAPURAM	OHSR	20	Top slab, verticals and Valves damaged	2.00
13	KUPPAM	GUDUPALLI	CHINNAGOLLAPALLE	AYYAVARIGOLLAPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
14	KUPPAM	GUDUPALLI	CHINNAGOLLAPALLE	CHINNAGOLLAPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
15	KUPPAM	GUDUPALLI	CHINNAGOLLAPALLE	JOGINDLU	OHSR	20	Top slab, verticals and Valves damaged	2.00

16	KUPPAM	GUDUPALLI	CHINNAGOLLAPALLE	MALAVANIKOTHUR	OHSR	20	Top slab, verticals and Valves damaged	2.00
17	KUPPAM	GUDUPALLI	CHINNAGOLLAPALLE	PEDDAGOLLAPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
18	KUPPAM	GUDUPALLI	DASIMANIPALLI	ATHINATHAM	OHSR	20	Top slab, verticals and Valves damaged	2.00
19	KUPPAM	GUDUPALLI	DASIMANIPALLI	BISANATHAM	OHSR	20	Top slab, verticals and Valves damaged	2.00
20	KUPPAM	GUDUPALLI	DASIMANIPALLI	DASIMANIPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
21	KUPPAM	GUDUPALLI	GUDUPALLE	BIJJIGANIPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
22	KUPPAM	GUDUPALLI	GUDUPALLE	GUDUPALLE H.W.	OHSR	20	Top slab, verticals and Valves damaged	2.00
23	KUPPAM	GUDUPALLI	GUDUPALLE	IRISIGANIPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
24	KUPPAM	GUDUPALLI	GUDUPALLE	MITTOOR	OHSR	20	Top slab, verticals and Valves damaged	2.00
25	KUPPAM	GUDUPALLI	GUNDLASAGARAM	GUNDLASAGARAM	OHSR	20	Top slab, verticals and Valves damaged	2.00
26	KUPPAM	GUDUPALLI	KANAMANAPALLE	KANAMANAPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
27	KUPPAM	GUDUPALLI	KANAMANAPALLE	KANAMANAPALLE H.W.	OHSR	20	Top slab, verticals and Valves damaged	2.00
28	KUPPAM	GUDUPALLI	KANAMANAPALLE	MIDDURU	OHSR	20	Top slab, verticals and Valves damaged	2.00
29	KUPPAM	GUDUPALLI	KANCHIBANDARLAPALLI	CHINNABANDARLAPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
30	KUPPAM	GUDUPALLI	KANCHIBANDARLAPALLI	KANCHIBANDARLAPALLI	OHSR	20	Top slab, verticals and Valves damaged	2.00
31	KUPPAM	GUDUPALLI	KODATHANAPALLI	AVULATHIMMANPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
32	KUPPAM	GUDUPALLI	KODATHANAPALLI	GUDICHEMBAGIRI	OHSR	20	Top slab, verticals and Valves damaged	2.00
33	KUPPAM	GUDUPALLI	KODATHANAPALLI	KODATHANAPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
34	KUPPAM	GUDUPALLI	KODATHANAPALLI	SALACHINTHANAPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00

35	KUPPAM	GUDUPALLI	KUPPIGANIPALLE	GUDIPALLE RLY.STATION	OHSR	20	Top slab, verticals and Valves damaged	2.00
36	KUPPAM	GUDUPALLI	KUPPIGANIPALLE	KOTACHEMBAGIRI	OHSR	20	Top slab, verticals and Valves damaged	2.00
37	KUPPAM	GUDUPALLI	KUPPIGANIPALLE	KUPPIGANIPALLE BCCOLONY	GLSR	20	Top slab, verticals and Valves damaged	2.00
38	KUPPAM	GUDUPALLI	KUPPIGANIPALLE	ONTIPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
39	KUPPAM	GUDUPALLI	KUPPIGANIPALLE	SIRIGIRIPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
40	KUPPAM	GUDUPALLI	O.N.KOTHURU	CHINNAKOTAMAKINEPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
41	KUPPAM	GUDUPALLI	O.N.KOTHURU	KONDASAMUDRAM	GLSR	20	Top slab, verticals and Valves damaged	2.00
42	KUPPAM	GUDUPALLI	O.N.KOTHURU	KOTAMAKANEPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
43	KUPPAM	GUDUPALLI	O.N.KOTHURU	O.N.KOTHUR	OHSR	20	Top slab, verticals and Valves damaged	2.00
44	KUPPAM	GUDUPALLI	O.N.KOTHURU	SRINIVASAPURAM	OHSR	20	Top slab, verticals and Valves damaged	2.00
45	KUPPAM	GUDUPALLI	O.N.KOTHURU	THALLIAGHARAM	OHSR	20	Top slab, verticals and Valves damaged	2.00
46	KUPPAM	GUDUPALLI	P.B. WADA	GUDIKOTHUR	OHSR	20	Top slab, verticals and Valves damaged	2.00
47	KUPPAM	GUDUPALLI	P.B. WADA	JATIKARTHANAPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
48	KUPPAM	GUDUPALLI	P.B. WADA	KAMMAGUTTAPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
49	KUPPAM	GUDUPALLI	P.B. WADA	KRISHNAIAHGARIKOTTALU	OHSR	20	Top slab, verticals and Valves damaged	2.00
50	KUPPAM	GUDUPALLI	P.B. WADA	PAPANUR	OHSR	20	Top slab, verticals and Valves damaged	2.00
51	KUPPAM	GUDUPALLI	P.B. WADA	PEDDABADANAWADA	OHSR	20	Top slab, verticals and Valves damaged	2.00
52	KUPPAM	GUDUPALLI	P.B. WADA	VEPAMANIKOTHUR	OHSR	20	Top slab, verticals and Valves damaged	2.00
53	KUPPAM	GUDUPALLI	POGURUPALLE	ANGANAMALAKOTHUR	OHSR	20	Top slab, verticals and Valves damaged	2.00

54	KUPPAM	GUDUPALLI	POGURUPALLE	CHINTHALAPALYAM	OHSR	20	Top slab, verticals and Valves damaged	2.00
55	KUPPAM	GUDUPALLI	POGURUPALLE	K.GOLLAPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
56	KUPPAM	GUDUPALLI	POGURUPALLE	POGURUPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
57	KUPPAM	GUDUPALLI	SANGANAPALLI	BOYANAPALLI	OHSR	20	Top slab, verticals and Valves damaged	2.00
58	KUPPAM	GUDUPALLI	SANGANAPALLI	BURUGULAPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
59	KUPPAM	GUDUPALLI	SANGANAPALLI	CHINNAPARTHIKUNTA	OHSR	20	Top slab, verticals and Valves damaged	2.00
60	KUPPAM	GUDUPALLI	SANGANAPALLI	JOGINDLU	OHSR	20	Top slab, verticals and Valves damaged	2.00
61	KUPPAM	GUDUPALLI	SANGANAPALLI	PEDDAPARTHIKUNTA	OHSR	20	Top slab, verticals and Valves damaged	2.00
62	KUPPAM	GUDUPALLI	SANGANAPALLI	SANGANAPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
63	KUPPAM	GUDUPALLI	SETTIPALLE	CHINNASETTIPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
64	KUPPAM	GUDUPALLI	SETTIPALLE	GOVINDAPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
65	KUPPAM	GUDUPALLI	SETTIPALLE	JOGYANURU	OHSR	20	Top slab, verticals and Valves damaged	2.00
66	KUPPAM	GUDUPALLI	SETTIPALLE	KAPPALANATHAM	OHSR	20	Top slab, verticals and Valves damaged	2.00
67	KUPPAM	GUDUPALLI	SETTIPALLE	SADANANDHASHRAM	OHSR	20	Top slab, verticals and Valves damaged	2.00
68	KUPPAM	GUDUPALLI	SETTIPALLE	SETTIPALLE	2 OHSR & 1 GLSR	40 + 20 + 10	Top slab, verticals and Valves damaged	5.00
69	KUPPAM	GUDUPALLI	SETTIPALLE	SETTIPALLE CROSS	OHSR	20	Top slab, verticals and Valves damaged	2.00
70	KUPPAM	GUDUPALLI	SODIGANIPALLE	ALUGUMANIPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
71	KUPPAM	GUDUPALLI	SODIGANIPALLE	ANAGARLAPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
72	KUPPAM	GUDUPALLI	SODIGANIPALLE	BURIDIGANIGUNTA	OHSR	20	Top slab, verticals and Valves damaged	2.00

73	KUPPAM	GUDUPALLI	SODIGANIPALLE	DIGUVACHIGARLAPALLI	OHSR	20	Top slab, verticals and Valves damaged	2.00
74	KUPPAM	GUDUPALLI	SODIGANIPALLE	DINNEPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
75	KUPPAM	GUDUPALLI	SODIGANIPALLE	MALDEPALLI	OHSR	20	Top slab, verticals and Valves damaged	2.00
76	KUPPAM	GUDUPALLI	SODIGANIPALLE	SODIGANI PALYEM	OHSR	20	Top slab, verticals and Valves damaged	2.00
77	KUPPAM	GUDUPALLI	SODIGANIPALLE	SODIGANIPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
78	KUPPAM	GUDUPALLI	SODIGANIPALLE	SONNARSANAPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
79	KUPPAM	GUDUPALLI	SODIGANIPALLE	THIMMINAYANIPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
80	KUPPAM	GUDUPALLI	YAMAGANIPALLE	ADAVI BADINAVADA	OHSR	20	Top slab, verticals and Valves damaged	2.00
81	KUPPAM	GUDUPALLI	YAMAGANIPALLE	SARIGAVARIKOTTALU	OHSR	20	Top slab, verticals and Valves damaged	2.00
82	KUPPAM	GUDUPALLI	YAMAGANIPALLE	SOLAPPAKOTTALU	OHSR	20	Top slab, verticals and Valves damaged	2.00
83	KUPPAM	GUDUPALLI	YAMAGANIPALLE	YAMAGANIPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
84	KUPPAM	RAMAKUPPAM	89 PEDDUR	PEDDURU H/W	OHSR	20	Top slab, verticals and Valves damaged	2.00
85	KUPPAM	RAMAKUPPAM	BAIPPAREDLAPALLE	BAIPPAREDLAPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
86	KUPPAM	RAMAKUPPAM	BAIPPAREDLAPALLE	JOGIINDLU	GLSR	10	Top slab, verticals and Valves damaged	1.00
87	KUPPAM	RAMAKUPPAM	BALLA	BALLA	OHSR	20	Top slab, verticals and Valves damaged	3.50
88	KUPPAM	RAMAKUPPAM	BALLA	LAKSHMINAGAR	GLSR	20	Top slab, verticals and Valves damaged	1.00
89	KUPPAM	RAMAKUPPAM	BALLA	PEDDAKURABALAPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
90	KUPPAM	RAMAKUPPAM	BALLA	SINGAMPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
91	KUPPAM	RAMAKUPPAM	BANDARLAPALLE	BAGALANATHAM	2 OHSR 20 KL Each	20 + 20	Top slab, verticals and Valves damaged	5.70

92	KUPPAM	RAMAKUPPAM	BANDARLAPALLE	BANDARLAPALLE	OHSR	20	Top slab, verticals and Valves damaged	3.00
93	KUPPAM	RAMAKUPPAM	BANDARLAPALLE	BOYANAPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.90
94	KUPPAM	RAMAKUPPAM	BANDARLAPALLE	GADDURU	OHSR	20	Top slab, verticals and Valves damaged	2.00
95	KUPPAM	RAMAKUPPAM	BANDARLAPALLE	GIDDAPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
96	KUPPAM	RAMAKUPPAM	BANDARLAPALLE	GOVINDARAJUPURAM	OHSR	20	Top slab, verticals and Valves damaged	3.05
97	KUPPAM	RAMAKUPPAM	BANDARLAPALLE	KANCHIDASANAPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
98	KUPPAM	RAMAKUPPAM	BANDARLAPALLE	LAKSHMIPURAM	GLSR	20	Top slab, verticals and Valves damaged	3.00
99	KUPPAM	RAMAKUPPAM	BANDARLAPALLE	LINGAPURAM	OHSR	20	Top slab, verticals and Valves damaged	2.00
100	KUPPAM	RAMAKUPPAM	BANDARLAPALLE	NAKKABALAPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.90
101	KUPPAM	RAMAKUPPAM	BANDARLAPALLE	NERNELLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
102	KUPPAM	RAMAKUPPAM	BANDARLAPALLE	PAMANA BOYANAPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
103	KUPPAM	RAMAKUPPAM	BANDARLAPALLE	PERURU	OHSR	20	Top slab, verticals and Valves damaged	2.00
104	KUPPAM	RAMAKUPPAM	BANDARLAPALLE	YANDHICOLONY	OHSR	20	Top slab, verticals and Valves damaged	2.50
105	KUPPAM	RAMAKUPPAM	CHELDIGANIPALLE	BURUGUMAKULAPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
106	KUPPAM	RAMAKUPPAM	CHELDIGANIPALLE	CHELDIGANIPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
107	KUPPAM	RAMAKUPPAM	GORIVIMAKULAPALLE	GORIVIMAKULAPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
108	KUPPAM	RAMAKUPPAM	GORIVIMAKULAPALLE	PEDDABALADAR	OHSR	20	Top slab, verticals and Valves damaged	2.00
109	KUPPAM	RAMAKUPPAM	GORIVIMAKULAPALLE	PEDDAGARGAPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
110	KUPPAM	RAMAKUPPAM	KENCHANABALLA	BHUMANDALAPURAM	OHSR	20	Top slab, verticals and Valves damaged	2.00

111	KUPPAM	RAMAKUPPAM	KENCHANABALLA	GANDHINAGAR	OHSR	20	Top slab, verticals and Valves damaged	3.50
112	KUPPAM	RAMAKUPPAM	KENCHANABALLA	PACHERUMAKULAPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
113	KUPPAM	RAMAKUPPAM	KENCHANABALLA	REDIVANIPODU	OHSR	20	Top slab, verticals and Valves damaged	3.50
114	KUPPAM	RAMAKUPPAM	KENCHANABALLA	VEERANAGAPURAM	OHSR	20	Top slab, verticals and Valves damaged	2.00
115	KUPPAM	RAMAKUPPAM	KONGANAPALLE	VENKATAPURAM	OHSR	20	Top slab, verticals and Valves damaged	2.00
116	KUPPAM	RAMAKUPPAM	MANENDRAM	MODDULAVANKA	GLSR	20	Top slab, verticals and Valves damaged	2.00
117	KUPPAM	RAMAKUPPAM	MUDDANAPALLE	MUDDANAPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
118	KUPPAM	RAMAKUPPAM	PANDYALAMADUGU	KAVVAMPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
119	KUPPAM	RAMAKUPPAM	PANDYALAMADUGU	MOTLAVANKA	GLSR	20	Top slab, verticals and Valves damaged	1.50
120	KUPPAM	RAMAKUPPAM	PANDYALAMADUGU	P.M.K.THANDA	OHSR	20	Top slab, verticals and Valves damaged	3.50
121	KUPPAM	RAMAKUPPAM	PANDYALAMADUGU	PALLAKUPPAM	OHSR	20	Top slab, verticals and Valves damaged	3.00
122	KUPPAM	RAMAKUPPAM	PANDYALAMADUGU	PANDYALAMDUGU	OHSR	20	Top slab, verticals and Valves damaged	3.00
123	KUPPAM	RAMAKUPPAM	PANDYALAMADUGU	PANDYALAMDUGU HW	GLSR	20	Top slab, verticals and Valves damaged	1.50
124	KUPPAM	RAMAKUPPAM	PANDYALAMADUGU	PULIMADUGUTHANDA	OHSR	20	Top slab, verticals and Valves damaged	2.95
125	KUPPAM	RAMAKUPPAM	PANDYALAMADUGU	S GOLLAPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
126	KUPPAM	RAMAKUPPAM	RAJUPETA	RAJUPETA	OHSR	20	Top slab, verticals and Valves damaged	2.00
127	KUPPAM	RAMAKUPPAM	RAMAKUPPAM	AYAPPAGANIPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
128	KUPPAM	RAMAKUPPAM	RAMAKUPPAM	KOTLAGURU	OHSR	20	Top slab, verticals and Valves damaged	2.00
129	KUPPAM	RAMAKUPPAM	RAMAKUPPAM	MITTAPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.50

130	KUPPAM	RAMAKUPPAM	RAMAKUPPAM	MODERN COLONY	OHSR	20	Top slab, verticals and Valves damaged	2.00
131	KUPPAM	RAMAKUPPAM	RAMAKUPPAM	RAMAKUPPAM	3 no 40 KL OHSR + 1 No 20 KL OHSR + 1 no 10 KL OHSR		Top slab, verticals and Valves damaged	12.00
132	KUPPAM	RAMAKUPPAM	RAMAKUPPAM	VENKATAPURAM	GLSR	10	Top slab, verticals and Valves damaged	1.00
133	KUPPAM	RAMAKUPPAM	SINGASAMUDRAM	GEEDIMAKULAPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
134	KUPPAM	RAMAKUPPAM	SINGASAMUDRAM	KUPPIGARIPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
135	KUPPAM	RAMAKUPPAM	SINGASAMUDRAM	REDDIVARIPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
136	KUPPAM	RAMAKUPPAM	UNCIGANIPALLE	ANIGANURU	OHSR	20	Top slab, verticals and Valves damaged	2.00
137	KUPPAM	RAMAKUPPAM	UNCIGANIPALLE	GOVINDAPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
138	KUPPAM	RAMAKUPPAM	UNCIGANIPALLE	JOGIINDLU	GLSR	10	Top slab, verticals and Valves damaged	2.00
139	KUPPAM	RAMAKUPPAM	UNCIGANIPALLE	JOWKUPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
140	KUPPAM	RAMAKUPPAM	UNCIGANIPALLE	PEDDAGANURU	OHSR	20	Top slab, verticals and Valves damaged	2.00
141	KUPPAM	RAMAKUPPAM	VEERNAMALA	ADDAGATTU THANDA	GLSR	20	Top slab, verticals and Valves damaged	2.00
142	KUPPAM	RAMAKUPPAM	VEERNAMALA	BANDAKOTHURUTANDA	GLSR	20	Top slab, verticals and Valves damaged	2.00
143	KUPPAM	RAMAKUPPAM	VEERNAMALA	CHELIMICHENU THANDA	OHSR	20	Top slab, verticals and Valves damaged	2.00
144	KUPPAM	RAMAKUPPAM	VEERNAMALA	CHIKKAPALLE THANDA	OHSR	20	Top slab, verticals and Valves damaged	2.00
145	KUPPAM	RAMAKUPPAM	VEERNAMALA	GURUKULAM ADUGU	OHSR	20	Top slab, verticals and Valves damaged	2.00
146	KUPPAM	RAMAKUPPAM	VEERNAMALA	GUTTURUTHANDA	OHSR	20	Top slab, verticals and Valves damaged	2.00
147	KUPPAM	RAMAKUPPAM	VEERNAMALA	KORNALAKONDATHANDA	OHSR	20	Top slab, verticals and Valves damaged	2.00
148	KUPPAM	RAMAKUPPAM	VEERNAMALA	KULLAGANURU	OHSR	20	Top slab, verticals and Valves	2.00

							damaged	
149	KUPPAM	RAMAKUPPAM	VEERNAMALA	PEDDA THANDA	GLSR	20	Top slab, verticals and Valves damaged	2.00
150	KUPPAM	RAMAKUPPAM	VEERNAMALA	PODICHENU	OHSR	20	Top slab, verticals and Valves damaged	2.00
151	KUPPAM	RAMAKUPPAM	VEERNAMALA	THULASINAIK THANDA	OHSR	20	Top slab, verticals and Valves damaged	2.00
152	KUPPAM	RAMAKUPPAM	VEERNAMALA	VEERANAMALA	OHSR	20	Top slab, verticals and Valves damaged	3.50
153	KUPPAM	RAMAKUPPAM	VEERNAMALA	VEMULAPALLE	OHSR	20	Top slab, verticals and Valves damaged	1.50
154	KUPPAM	RAMAKUPPAM	VIJALAPURAM	ANKIREDDIPALLE	OHSR	20	Top slab, verticals and Valves damaged	2.00
155	KUPPAM	RAMAKUPPAM	VIJALAPURAM	BALAOBANAPALLE	OHSR	20	Top slab, verticals and Valves damaged	1.00
156	KUPPAM	RAMAKUPPAM	VIJALAPURAM	SANTHAMITTA	OHSR	20	Top slab, verticals and Valves damaged	2.00
157	KUPPAM	KUPPAM	ADAVIBUDUGUR	ADAVIBUDUGUR	OHSR	20KL	Top slab , vertical connection	3.20
158	KUPPAM	KUPPAM	ADAVIBUDUGUR	ADAVIBUDUGUR H.W	OHSR	20KL	Top slab , vertical connection	3.15
159	KUPPAM	KUPPAM	ADAVIBUDUGUR	MOOLACHENU	OHSR	20KL	Top slab , vertical connection	2.95
160	KUPPAM	KUPPAM	ADAVIBUDUGUR	VINAYAKAPURAM	OHSR	20KL	Top slab , vertical connection	3.05
161	KUPPAM	KUPPAM	ADAVIBUDUGUR	YEERAGUTACHENU	OHSR	20KL	Top slab , vertical connection	3.00
162	KUPPAM	KUPPAM	ANIMIGANIPALLE	ANIMIGANIPALLE	OHSR	20KL	Top slab , vertical connection	3.15
163	KUPPAM	KUPPAM	ANIMIGANIPALLE	ANIMIGANIPALLE BC COLON	OHSR	20KL	Top slab , vertical connection	3.05
164	KUPPAM	KUPPAM	ANIMIGANIPALLE	ANIMIGANIPALLE S.C.COLONY	OHSR	20KL	Top slab , vertical connection	3.00
165	KUPPAM	KUPPAM	CHANDAM	CHANDAM	OHSR	20KL	Top slab , vertical connection	3.20
166	KUPPAM	KUPPAM	CHANDAM	CHANDAM HW	OHSR	20KL	Top slab , vertical connection	3.15
167	KUPPAM	KUPPAM	CHANDAM	KOTHAINDLU	OHSR	20KL	Top slab , vertical connection	3.05
168	KUPPAM	KUPPAM	CHEELAPALLE	BEVANAPALLE	OHSR	20KL	Top slab , vertical connection	3.10
169	KUPPAM	KUPPAM	CHEELAPALLE	CHEELEPALLE	OHSR	20KL	Top slab , vertical connection	3.15
170	KUPPAM	KUPPAM	CHEELAPALLE	PALARLAPALLE	OHSR	20KL	Top slab , vertical connection	3.15

171	KUPPAM	KUPPAM	CHEELAPALLE	PARAMASUMUDRAM (BC COLONY)	OHSR	20KL	Top slab , vertical connection	3.05
172	KUPPAM	KUPPAM	CHEELAPALLE	VADDEPALLE	OHSR	20KL	Top slab , vertical connection	3.20
173	KUPPAM	KUPPAM	CHEKKUNATHAM	ADAVIMULAKAPALLE	OHSR	20KL	Top slab , vertical connection	3.15
174	KUPPAM	KUPPAM	CHEKKUNATHAM	Babunagar	OHSR	20KL	Top slab , vertical connection	2.95
175	KUPPAM	KUPPAM	CHEKKUNATHAM	Balappakottalu	OHSR	20KL	Top slab , vertical connection	3.05
176	KUPPAM	KUPPAM	CHEKKUNATHAM	CHEKKUNMATHAM	OHSR	20KL	Top slab , vertical connection	3.05
177	KUPPAM	KUPPAM	CHEKKUNATHAM	CHEKKUNMATHAM HW	OHSR	20KL	Top slab , vertical connection	3.10
178	KUPPAM	KUPPAM	CHEKKUNATHAM	GOUDAPPANURU	OHSR	20KL	Top slab , vertical connection	3.15
179	KUPPAM	KUPPAM	CHEKKUNATHAM	Kalanuru	OHSR	20KL	Top slab , vertical connection	3.00
180	KUPPAM	KUPPAM	CHEKKUNATHAM	KANAMAPACHARLAPALLE	OHSR	20KL	Top slab , vertical connection	2.95
181	KUPPAM	KUPPAM	CHEKKUNATHAM	Kusuru	OHSR	20KL	Top slab , vertical connection	3.20
182	KUPPAM	KUPPAM	CHEKKUNATHAM	Maddulavankakottalu	OHSR	20KL	Top slab , vertical connection	3.15
183	KUPPAM	KUPPAM	CHEKKUNATHAM	PEDDA BOGGUPALLE	OHSR	20KL	Top slab , vertical connection	3.00
184	KUPPAM	KUPPAM	CHEKKUNATHAM	THUMMALAPALLE	OHSR	20KL	Top slab , vertical connection	3.00
185	KUPPAM	KUPPAM	CHEKKUNATHAM	ZATARIMADUGU	OHSR	20KL	Top slab , vertical connection	3.15
186	KUPPAM	KUPPAM	CHEMANAYANIPALLE	ABBUGUNTA	OHSR	20KL	Top slab , vertical connection	3.10
187	KUPPAM	KUPPAM	CHEMANAYANIPALLE	BAIRUGANIPALLE	OHSR	20KL	Top slab , vertical connection	3.05
188	KUPPAM	KUPPAM	CHEMANAYANIPALLE	GERISAVAVI	OHSR	20KL	Top slab , vertical connection	3.00
189	KUPPAM	KUPPAM	CHEMANAYANIPALLE	LAKSHMIPURAM B.CCOLONY	OHSR	20KL	Top slab , vertical connection	3.20
190	KUPPAM	KUPPAM	CHEMANAYANIPALLE	LAKSHMIPURAM CROSS	OHSR	20KL	Top slab , vertical connection	3.20
191	KUPPAM	KUPPAM	CHEMANAYANIPALLE	LAKSHMIPURAM H.W	OHSR	20KL	Top slab , vertical connection	3.15
192	KUPPAM	KUPPAM	CHEMANAYANIPALLE	LAXMIPURAM@C.N.PALLI	OHSR	20KL	Top slab , vertical connection	2.95
193	KUPPAM	KUPPAM	CHEMANAYANIPALLE	LAXMIPURAMCOLONY	OHSR	20KL	Top slab , vertical connection	3.00
194	KUPPAM	KUPPAM	CHEMANAYANIPALLE	SURAPPAKOTULU	OHSR	20KL	Top slab , vertical connection	3.05
195	KUPPAM	KUPPAM	CHEMANAYANIPALLE	YANADICOLONY	OHSR	20KL	Top slab , vertical connection	3.15

196	KUPPAM	KUPPAM	DALAVAIKOTHAPALLE	CHINNAKURBALAPALLE	OHSR	20KL	Top slab , vertical connection	3.20
197	KUPPAM	KUPPAM	DALAVAIKOTHAPALLE	DALAVAIKOTHAPALLE	OHSR	20KL	Top slab , vertical connection	3.15
198	KUPPAM	KUPPAM	DALAVAIKOTHAPALLE	DALAVAIKOTHAPALLE HW	OHSR	20KL	Top slab , vertical connection	3.00
199	KUPPAM	KUPPAM	DALAVAIKOTHAPALLE	MODEL COLONY	OHSR	20KL	Top slab , vertical connection	3.00
200	KUPPAM	KUPPAM	DALAVAIKOTHAPALLE	MODEL COLONY (SC)	OHSR	20KL	Top slab , vertical connection	2.95
201	KUPPAM	KUPPAM	DALAVAIKOTHAPALLE	N.T.R. COLONY	OHSR	20KL	Top slab , vertical connection	3.10
202	KUPPAM	KUPPAM	DALAVAIKOTHAPALLE	RADHA KRISHNA COLONY	OHSR	20KL	Top slab , vertical connection	3.05
203	KUPPAM	KUPPAM	DALAVAIKOTHAPALLE	SRILANKA COLONY	OHSR	20KL	Top slab , vertical connection	3.05
204	KUPPAM	KUPPAM	DALAVAIKOTHAPALLE	URBANCOLONY	OHSR	20KL	Top slab , vertical connection	3.20
205	KUPPAM	KUPPAM	DASEGOWNIYUR	BAIRAPPAKOTALU	OHSR	20KL	Top slab , vertical connection	3.00
206	KUPPAM	KUPPAM	DASEGOWNIYUR	BALLAMDANDAKOTTALU	OHSR	20KL	Top slab , vertical connection	3.15
207	KUPPAM	KUPPAM	DASEGOWNIYUR	BAYYANURU	OHSR	20KL	Top slab , vertical connection	3.20
208	KUPPAM	KUPPAM	DASEGOWNIYUR	BAYYANURU ST COLONY	OHSR	20KL	Top slab , vertical connection	3.10
209	KUPPAM	KUPPAM	DASEGOWNIYUR	BOGGUPALLE	OHSR	20KL	Top slab , vertical connection	3.20
210	KUPPAM	KUPPAM	DASEGOWNIYUR	DASEGOWNIYUR	OHSR	20KL	Top slab , vertical connection	3.05
211	KUPPAM	KUPPAM	DASEGOWNIYUR	Egulerappakottalu	OHSR	20KL	Top slab , vertical connection	3.05
212	KUPPAM	KUPPAM	DASEGOWNIYUR	GUTTAPALLE	OHSR	20KL	Top slab , vertical connection	2.95
213	KUPPAM	KUPPAM	DASEGOWNIYUR	GUTTAPALLE COLONY	OHSR	20KL	Top slab , vertical connection	3.00
214	KUPPAM	KUPPAM	DASEGOWNIYUR	JALLAPPAKOTALU	OHSR	20KL	Top slab , vertical connection	3.05
215	KUPPAM	KUPPAM	DASEGOWNIYUR	Narayanapuram	OHSR	20KL	Top slab , vertical connection	3.15
216	KUPPAM	KUPPAM	DASEGOWNIYUR	RAMNAGAR	OHSR	20KL	Top slab , vertical connection	2.95
217	KUPPAM	KUPPAM	DASEGOWNIYUR	VAGARAPPAKOTALU	OHSR	20KL	Top slab , vertical connection	3.15
218	KUPPAM	KUPPAM	GARIGACHENUPALLE	DOMARAAGRAHARAM	OHSR	20KL	Top slab , vertical connection	3.05
219	KUPPAM	KUPPAM	GARIGACHENUPALLE	EGUVA KAKIMADUGU	OHSR	20KL	Top slab , vertical connection	3.15
220	KUPPAM	KUPPAM	GARIGACHENUPALLE	GARIGACHENUPALLE	OHSR	20KL	Top slab , vertical connection	3.15

221	KUPPAM	KUPPAM	GARIGACHENUPALLE	KAKIMADUGU	OHSR	20KL	Top slab , vertical connection	3.20
222	KUPPAM	KUPPAM	GARIGACHENUPALLE	VEPPANAPALLI	OHSR	20KL	Top slab , vertical connection	5.70
223	KUPPAM	KUPPAM	GONUGUR	GONUGUR	OHSR	20KL	Top slab , vertical connection	3.20
224	KUPPAM	KUPPAM	GONUGUR	GONUGUR BC COLONY	OHSR	20KL	Top slab , vertical connection	3.05
225	KUPPAM	KUPPAM	GONUGUR	GONUGUR HW	OHSR	20KL	Top slab , vertical connection	3.15
226	KUPPAM	KUPPAM	GONUGUR	GUTTAPALLE	OHSR	20KL	Top slab , vertical connection	3.10
227	KUPPAM	KUPPAM	GUDLANAYARIPALLE	GUNDLANAYANIPALLE	OHSR	20KL	Top slab , vertical connection	3.05
228	KUPPAM	KUPPAM	GUDLANAYARIPALLE	URINAYANIKOTHUR	OHSR	20KL	Top slab , vertical connection	3.15
229	KUPPAM	KUPPAM	GUDLANAYARIPALLE	URINAYANIPALLE	OHSR	20KL	Top slab , vertical connection	3.20
230	KUPPAM	KUPPAM	JARUGU	CHALRLAPALLE	OHSR	20KL	Top slab , vertical connection	3.05
231	KUPPAM	KUPPAM	JARUGU	JARUGU	OHSR	20KL	Top slab , vertical connection	3.00
232	KUPPAM	KUPPAM	JARUGU	JOGINDLU	OHSR	20KL	Top slab , vertical connection	3.10
233	KUPPAM	KUPPAM	JARUGU	PORAKUNTAPALLE	OHSR	20KL	Top slab , vertical connection	3.20
234	KUPPAM	KUPPAM	JARUGU	YANAMANASANAPALLE	OHSR	20KL	Top slab , vertical connection	3.15
235	KUPPAM	KUPPAM	KAMATHAMURU	GULLE PALLE	OHSR	20KL	Top slab , vertical connection	3.20
236	KUPPAM	KUPPAM	KAMATHAMURU	GUNDLAPALLE	OHSR	20KL	Top slab , vertical connection	3.15
237	KUPPAM	KUPPAM	KAMATHAMURU	KAMATHAMUR	OHSR	20KL	Top slab , vertical connection	2.95
238	KUPPAM	KUPPAM	KAMATHAMURU	KAMATHAMURCOLONY	OHSR	20KL	Top slab , vertical connection	3.20
239	KUPPAM	KUPPAM	KAMATHAMURU	KATHIMANIPALLE	OHSR	20KL	Top slab , vertical connection	3.05
240	KUPPAM	KUPPAM	KANGUNDI	AMBAPURAM	OHSR	20KL	Top slab , vertical connection	2.95
241	KUPPAM	KUPPAM	KANGUNDI	BRAHMADEVARACHERUVU	OHSR	20KL	Top slab , vertical connection	3.15
242	KUPPAM	KUPPAM	KANGUNDI	DEVARAJUPURAM BC COLONY	OHSR	20KL	Top slab , vertical connection	3.10
243	KUPPAM	KUPPAM	KANGUNDI	DEVARAJUPURAM QUARYVATTAM	OHSR	20KL	Top slab , vertical connection	3.20
244	KUPPAM	KUPPAM	KANGUNDI	GANESHPURAM	OHSR	20KL	Top slab , vertical connection	3.00
245	KUPPAM	KUPPAM	KANGUNDI	Giddeganipenta	OHSR	20KL	Top slab , vertical connection	3.05
246	KUPPAM	KUPPAM	KANGUNDI	KANGUNDI	OHSR	20KL	Top slab ,	3.05

							vertical connection	
247	KUPPAM	KUPPAM	KANGUNDI	KANGUNDI R.F.	OHSR	20KL	Top slab , vertical connection	3.00
248	KUPPAM	KUPPAM	KANGUNDI	Kausigandlapalli	OHSR	20KL	Top slab , vertical connection	3.10
249	KUPPAM	KUPPAM	KANGUNDI	KRISHNAPURAM	OHSR	20KL	Top slab , vertical connection	3.05
250	KUPPAM	KUPPAM	KANGUNDI	Mangammavoru	OHSR	20KL	Top slab , vertical connection	3.15
251	KUPPAM	KUPPAM	KANGUNDI	Nakkalagutta	OHSR	20KL	Top slab , vertical connection	5.50
252	KUPPAM	KUPPAM	KANGUNDI	Narayanapuram	OHSR	20KL	Top slab , vertical connection	3.10
253	KUPPAM	KUPPAM	KANGUNDI	NAYANURU	OHSR	20KL	Top slab , vertical connection	2.95
254	KUPPAM	KUPPAM	KANGUNDI	Parvathipuram	OHSR	20KL	Top slab , vertical connection	3.05
255	KUPPAM	KUPPAM	KANGUNDI	PARVATHIPURAM	OHSR	20KL	Top slab , vertical connection	3.00
256	KUPPAM	KUPPAM	KANGUNDI	PEDDAVANKA	OHSR	20KL	Top slab , vertical connection	3.20
257	KUPPAM	KUPPAM	KANGUNDI	RAMULAGUTTA CHENU	OHSR	20KL	Top slab , vertical connection	3.15
258	KUPPAM	KUPPAM	KANGUNDI	Sahipuram	OHSR	20KL	Top slab , vertical connection	3.20
259	KUPPAM	KUPPAM	KANGUNDI	Samadhulu	OHSR	20KL	Top slab , vertical connection	3.15
260	KUPPAM	KUPPAM	KANGUNDI	Tagaramanimula	OHSR	20KL	Top slab , vertical connection	2.95
261	KUPPAM	KUPPAM	KANGUNDI	Terlavaniband a	OHSR	20KL	Top slab , vertical connection	3.00
262	KUPPAM	KUPPAM	KANGUNDI	VENKATARAJAPURAM BC COLONY(SC COLONY)	OHSR	20KL	Top slab , vertical connection	3.05
263	KUPPAM	KUPPAM	KANGUNDI	VENKATARAJAPURAM SC COLONY	OHSR	20KL	Top slab , vertical connection	3.15
264	KUPPAM	KUPPAM	KANGUNDI	VENKATESAPURAM	OHSR	20KL	Top slab , vertical connection	3.00
265	KUPPAM	KUPPAM	KOTTALURU	GUNDLAMADUGU	OHSR	20KL	Top slab , vertical connection	3.15
266	KUPPAM	KUPPAM	KOTTALURU	KOTTALURU	OHSR	20KL	Top slab , vertical connection	3.05
267	KUPPAM	KUPPAM	KOTTALURU	MESTRINAYANURU	OHSR	20KL	Top slab , vertical connection	3.05
268	KUPPAM	KUPPAM	KOTTALURU	MOTURU	OHSR	20KL	Top slab , vertical connection	3.10
269	KUPPAM	KUPPAM	KOTTALURU	NOORAVULA GUNDLACHENU	OHSR	20KL	Top slab , vertical connection	3.00
270	KUPPAM	KUPPAM	KOTTALURU	RALLACHENU	OHSR	20KL	Top slab , vertical connection	3.20
271	KUPPAM	KUPPAM	KOTTALURU	Samidammavanka	OHSR	20KL	Top slab , vertical	3.20

							connection	
272	KUPPAM	KUPPAM	KOTTALURU	Sappanigunta	OHSR	20KL	Top slab , vertical connection	3.15
273	KUPPAM	KUPPAM	KOTTALURU	SIDDAPPANURU	OHSR	20KL	Top slab , vertical connection	3.15
274	KUPPAM	KUPPAM	KOTTALURU	Yanadipuram	OHSR	20KL	Top slab , vertical connection	3.15
275	KUPPAM	KUPPAM	KOTTALURU	YERRAMANNUGUNTALU (NAKKABONMITA)	OHSR	20KL	Top slab , vertical connection	2.95
276	KUPPAM	KUPPAM	KRISHNADASANAPALLE	CHIMPANAGALLU	OHSR	20KL	Top slab , vertical connection	3.20
277	KUPPAM	KUPPAM	KRISHNADASANAPALLE	GAGAPURAM	OHSR	20KL	Top slab , vertical connection	3.00
278	KUPPAM	KUPPAM	KRISHNADASANAPALLE	KRISHNADASANAPALLE	OHSR	20KL	Top slab , vertical connection	2.95
279	KUPPAM	KUPPAM	KRISHNADASANAPALLE	MATARLAPALLE	OHSR	20KL	Top slab , vertical connection	3.15
280	KUPPAM	KUPPAM	KRISHNADASANAPALLE	RAJANAM	OHSR	20KL	Top slab , vertical connection	3.05
281	KUPPAM	KUPPAM	KRISHNADASANAPALLE	VARAMANUR	OHSR	20KL	Top slab , vertical connection	3.10
282	KUPPAM	KUPPAM	KRISHNADASANAPALLE	YANADIPALLE	OHSR	20KL	Top slab , vertical connection	3.00
283	KUPPAM	KUPPAM	KUPPAM	BAIRUGANIPALLE HW	OHSR	20KL	Top slab , vertical connection	3.15
284	KUPPAM	KUPPAM	KUPPAM	KUPPAM	OHSR	350KL,150kl	Top slab , vertical connection	14.30
285	KUPPAM	KUPPAM	MALLANURU	Bikkilikutta	OHSR	20KL	Top slab , vertical connection	3.00
286	KUPPAM	KUPPAM	MALLANURU	CHINNAOBBA	OHSR	20KL	Top slab , vertical connection	3.05
287	KUPPAM	KUPPAM	MALLANURU	Giduru	OHSR	20KL	Top slab , vertical connection	2.95
288	KUPPAM	KUPPAM	MALLANURU	HANUMANNAKOTTALU	OHSR	20KL	Top slab , vertical connection	3.00
289	KUPPAM	KUPPAM	MALLANURU	KODIGANOORU	OHSR	20KL	Top slab , vertical connection	3.15
290	KUPPAM	KUPPAM	MALLANURU	KOTHACHENU	OHSR	20KL	Top slab , vertical connection	3.05
291	KUPPAM	KUPPAM	MALLANURU	KRISHNAPURAM	OHSR	20KL	Top slab , vertical connection	3.05
292	KUPPAM	KUPPAM	MALLANURU	MALLANURU	OHSR	20KL	Top slab , vertical connection	3.20
293	KUPPAM	KUPPAM	MALLANURU	METTAKADINURU	OHSR	20KL	Top slab , vertical connection	3.15
294	KUPPAM	KUPPAM	MALLANURU	MOTLACHENU	OHSR	20KL	Top slab , vertical connection	3.10
295	KUPPAM	KUPPAM	MALLANURU	MUTHURU	OHSR	20KL	Top slab , vertical connection	3.00
296	KUPPAM	KUPPAM	MALLANURU	PARTHICHENU	OHSR	20KL	Top slab , vertical connection	3.00

297	KUPPAM	KUPPAM	MALLANURU	PEDDANNAKOTTALU	OHSR	20KL	Top slab , vertical connection	3.20
298	KUPPAM	KUPPAM	MALLANURU	PONNANGUR (PONNAGURU YSR COLONY)	OHSR	20KL	Top slab , vertical connection	6.00
299	KUPPAM	KUPPAM	MALLANURU	SINGARAPURAM	OHSR	20KL	Top slab , vertical connection	3.15
300	KUPPAM	KUPPAM	MALLANURU	T.SADAMUR	OHSR	20KL	Top slab , vertical connection	2.95
301	KUPPAM	KUPPAM	MALLANURU	VALURU	OHSR	20KL	Top slab , vertical connection	3.20
302	KUPPAM	KUPPAM	MANKALADODDI	CHINNAGOPANAPALLE	OHSR	20KL	Top slab , vertical connection	3.20
303	KUPPAM	KUPPAM	MANKALADODDI	EGUVMANKALADODDI	OHSR	20KL	Top slab , vertical connection	3.10
304	KUPPAM	KUPPAM	MANKALADODDI	KONAYAKUNTA	OHSR	20KL	Top slab , vertical connection	3.20
305	KUPPAM	KUPPAM	MANKALADODDI	MANKALADODDI	OHSR	20KL	Top slab , vertical connection	3.05
306	KUPPAM	KUPPAM	MANKALADODDI	MULAKALAPALLE	OHSR	20KL	Top slab , vertical connection	3.15
307	KUPPAM	KUPPAM	MANKALADODDI	MULAKALAPALLE KOTALU	OHSR	20KL	Top slab , vertical connection	3.05
308	KUPPAM	KUPPAM	MANKALADODDI	PEDDAGOPANAPALLE	OHSR	20KL	Top slab , vertical connection	3.00
309	KUPPAM	KUPPAM	MANKALADODDI	SETTIGANIKUNTA	OHSR	20KL	Top slab , vertical connection	3.15
310	KUPPAM	KUPPAM	MANKALADODDI	UPPUKUNTA	OHSR	20KL	Top slab , vertical connection	3.00
311	KUPPAM	KUPPAM	MITTAPALLE	ADAMANDALAKUPPAM	OHSR	20KL	Top slab , vertical connection	3.05
312	KUPPAM	KUPPAM	MITTAPALLE	AVULANATHAM	OHSR	20KL	Top slab , vertical connection	3.05
313	KUPPAM	KUPPAM	MITTAPALLE	MITTAPALLE	OHSR	20KL	Top slab , vertical connection	5.90
314	KUPPAM	KUPPAM	MITTAPALLE	THIMMAPURAM	OHSR	20KL	Top slab , vertical connection	2.95
315	KUPPAM	KUPPAM	MITTAPALLE	VEPANAPALLI	OHSR	20KL	Top slab , vertical connection	3.00
316	KUPPAM	KUPPAM	MITTAPALLE	VEPURU	OHSR	20KL	Top slab , vertical connection	3.20
317	KUPPAM	KUPPAM	N.KOTHAPALLE	KADIRIPURAM	OHSR	20KL	Top slab , vertical connection	3.15
318	KUPPAM	KUPPAM	N.KOTHAPALLE	N.KOTHAPALLE	OHSR	20KL	Top slab , vertical connection	3.15
319	KUPPAM	KUPPAM	N.KOTHAPALLE	NIMMAKAMPALLE	OHSR	20KL	Top slab , vertical connection	3.20
320	KUPPAM	KUPPAM	N.KOTHAPALLE	SAJJALAPALLE	OHSR	20KL	Top slab , vertical connection	3.00
321	KUPPAM	KUPPAM	NADIMUR	BIRADAANAPALLE	OHSR	20KL	Top slab , vertical connection	3.20

322	KUPPAM	KUPPAM	NADIMUR	BODAGUTTAPALLE	OHSR	20KL	Top slab , vertical connection	2.95
323	KUPPAM	KUPPAM	NADIMUR	GUDLAKADIREPALLE	OHSR	20KL	Top slab , vertical connection	3.20
324	KUPPAM	KUPPAM	NADIMUR	JOGINDLU	OHSR	20KL	Top slab , vertical connection	3.10
325	KUPPAM	KUPPAM	NADIMUR	NADIMUR	OHSR	20KL	Top slab , vertical connection	3.00
326	KUPPAM	KUPPAM	NADIMUR	PAINAASI	OHSR	20KL	Top slab , vertical connection	3.05
327	KUPPAM	KUPPAM	NADIMUR	RAMABADRANOORU	OHSR	20KL	Top slab , vertical connection	3.05
328	KUPPAM	KUPPAM	NADIMUR	VASANDUGOLLAPALLE	OHSR	20KL	Top slab , vertical connection	3.00
329	KUPPAM	KUPPAM	NADIMUR	VEERANAGAPURAM	OHSR	20KL	Top slab , vertical connection	3.15
330	KUPPAM	KUPPAM	NOOLAKUNTA	NOOLAKUNTA	OHSR	20KL	Top slab , vertical connection	5.80
331	KUPPAM	KUPPAM	PAIPALYAM	CHINNA BOGGUPALLE	OHSR	20KL	Top slab , vertical connection	3.10
332	KUPPAM	KUPPAM	PAIPALYAM	CHINNAONI	OHSR	20KL	Top slab , vertical connection	3.20
333	KUPPAM	KUPPAM	PAIPALYAM	PAIPALYAM (ZPHS SCHOOL)	OHSR	20KL	Top slab , vertical connection	5.70
334	KUPPAM	KUPPAM	PAIPALYAM	PEDDAONNI KOTALU	OHSR	20KL	Top slab , vertical connection	3.15
335	KUPPAM	KUPPAM	PAIPALYAM	THANGEDIKUPPAM	OHSR	20KL	Top slab , vertical connection	3.05
336	KUPPAM	KUPPAM	PEDDA BANGARUNATHAM	CHINNA BANGARUNTHAM	OHSR	20KL	Top slab , vertical connection	3.15
337	KUPPAM	KUPPAM	PEDDA BANGARUNATHAM	KUNGEGOWNIYUR (PART)	OHSR	20KL	Top slab , vertical connection	3.05
338	KUPPAM	KUPPAM	PEDDA BANGARUNATHAM	MARWADA	OHSR	20KL	Top slab , vertical connection	2.95
339	KUPPAM	KUPPAM	PEDDA BANGARUNATHAM	PEDDA BANGARUNATHAM	OHSR	20KL	Top slab , vertical connection	3.20
340	KUPPAM	KUPPAM	SAMAGUNTTAPALLE	BANDASETTIALLE	OHSR	20KL	Top slab , vertical connection	3.15
341	KUPPAM	KUPPAM	SAMAGUNTTAPALLE	CHINNASEEGALAPALLE	OHSR	20KL	Top slab , vertical connection	3.05
342	KUPPAM	KUPPAM	SAMAGUNTTAPALLE	ELLAJJANURU (ADAVIKOTTALU)	OHSR	20KL	Top slab , vertical connection	3.20
343	KUPPAM	KUPPAM	SAMAGUNTTAPALLE	JALAPPA KOTTALURU	OHSR	20KL	Top slab , vertical connection	3.00
344	KUPPAM	KUPPAM	SAMAGUNTTAPALLE	NARAYANAPURAM	OHSR	20KL	Top slab , vertical connection	3.10
345	KUPPAM	KUPPAM	SAMAGUNTTAPALLE	PEDDANNAKOTALU	OHSR	20KL	Top slab , vertical connection	3.15
346	KUPPAM	KUPPAM	SAMAGUNTTAPALLE	SAMMAGUTTAPALLE	OHSR	20KL	Top slab , vertical connection	5.60
347	KUPPAM	KUPPAM	SAMAGUNTTAPALLE	SEEGALAPALLE	OHSR	20KL	Top slab , vertical	3.00

							connection	
348	KUPPAM	KUPPAM	SAMAGUNTTAPALLE	THANJAMKOTTALU	OHSR	20KL	Top slab , vertical connection	3.05
349	KUPPAM	KUPPAM	THAMBIGANIPALLE	THAMBIGANIPALLE	OHSR	20KL	Top slab , vertical connection	3.00
350	KUPPAM	KUPPAM	THAMBIGANIPALLE	THAMBIGANIPALLE COLONY	OHSR	20KL	Top slab , vertical connection	3.05
351	KUPPAM	KUPPAM	THAMBIGANIPALLE	THAMBIGANIPALLE HW	OHSR	20KL	Top slab , vertical connection	3.20
352	KUPPAM	KUPPAM	THAMBIGANIPALLE	THAMBIGANIPALLE KOTALU	OHSR	20KL	Top slab , vertical connection	3.15
353	KUPPAM	KUPPAM	THAMBIGANIPALLE	THAMNIGANIPALLE P.H.	OHSR	20KL	Top slab , vertical connection	3.00
354	KUPPAM	KUPPAM	URALAOBANAPALLE	GATTAPPANAYANIPALLE	OHSR	20KL	Top slab , vertical connection	3.20
355	KUPPAM	KUPPAM	URALAOBANAPALLE	KOORMANIPALLE	OHSR	20KL	Top slab , vertical connection	2.95
356	KUPPAM	KUPPAM	URALAOBANAPALLE	KOORMANIPALLE (BC COLONY)	OHSR	20KL	Top slab , vertical connection	3.00
357	KUPPAM	KUPPAM	URALAOBANAPALLE	MARAPALLE	OHSR	20KL	Top slab , vertical connection	3.05
358	KUPPAM	KUPPAM	URALAOBANAPALLE	URLAOBANAPALLE	OHSR	20KL	Top slab , vertical connection	3.15
359	KUPPAM	KUPPAM	VANAGUTTAPALLE	JAMPANURU	OHSR	20KL	Top slab , vertical connection	3.05
360	KUPPAM	KUPPAM	VANAGUTTAPALLE	RAGIMANUMITTA	OHSR	20KL	Top slab , vertical connection	3.15
361	KUPPAM	KUPPAM	VANAGUTTAPALLE	VANAGUTTAPALLE	OHSR	20KL	Top slab , vertical connection	3.20
362	KUPPAM	KUPPAM	VASANADU	CHINNAVASANADU	OHSR	20KL	Top slab , vertical connection	3.20
363	KUPPAM	KUPPAM	VASANADU	VASANADU	OHSR	20KL	Top slab , vertical connection	3.10
364	KUPPAM	KUPPAM	VENDUGAMPALLE	DHARAMARAJUKOTTALU	OHSR	20KL	Top slab , vertical connection	3.00
365	KUPPAM	KUPPAM	VENDUGAMPALLE	JAMBUCHERUVUKOTALU PARTII	OHSR	20KL	Top slab , vertical connection	3.20
366	KUPPAM	KUPPAM	VENDUGAMPALLE	MALLANURAPAKOTTALU	OHSR	20KL	Top slab , vertical connection	2.95
367	KUPPAM	KUPPAM	VENDUGAMPALLE	VENDUGAMPALLE (BC COLONY)	OHSR	20KL	Top slab , vertical connection	3.15
368	KUPPAM	KUPPAM	VENDUGAMPALLE	VENDUGAMPALLE KOTALU	OHSR	20KL	Top slab , vertical connection	3.05
369	KUPPAM	SANTHIPURAM	ANIKERA	BELLAKOGILA	OHSR	20KL	Top slab , vertical connection	3.1
370	KUPPAM	SANTHIPURAM	ANIKERA	VADAGANDLAPALLE	OHSR	20KL	Top slab , vertical connection	3.04
371	KUPPAM	SANTHIPURAM	ANIKERA	SETTEPALLE	OHSR	20KL	Top slab , vertical connection	3.06
372	KUPPAM	SANTHIPURAM	ANIKERA	BRAHMANAKOTHURU	OHSR	20KL	Top slab , vertical connection	3.08

373	KUPPAM	SANTHIPURAM	ANIKERA	ANIKERA	OHSR	20KL	Top slab , vertical connection	3.1
374	KUPPAM	SANTHIPURAM	REGADADINNEPALLE	NALLAPPAREDDIYURU	OHSR	20KL	Top slab , vertical connection	3.04
375	KUPPAM	SANTHIPURAM	REGADADINNEPALLE	REGADADINNEPALLE	OHSR	20KL	Top slab , vertical connection	3.06
376	KUPPAM	SANTHIPURAM	121 PEDDURU	BENDANAKUPPAM	OHSR	20KL	Top slab , vertical connection	3.08
377	KUPPAM	SANTHIPURAM	121 PEDDURU	121 PEDDURU	OHSR	20KL	Top slab , vertical connection	3.05
378	KUPPAM	SANTHIPURAM	121 PEDDURU	JB KOTHURU	OHSR	20KL	Top slab , vertical connection	3.1
379	KUPPAM	SANTHIPURAM	KONERU KUPPAM	KONERUKUPPAM	OHSR	20KL	Top slab , vertical connection	3.04
380	KUPPAM	SANTHIPURAM	KONERU KUPPAM	KOLALATHIMMANAPALLE	OHSR	20KL	Top slab , vertical connection	3.06
381	KUPPAM	SANTHIPURAM	RALLABADUGURU	SATHU	OHSR	20KL	Top slab , vertical connection	3.08
382	KUPPAM	SANTHIPURAM	RALLABADUGURU	REDDIVARIPALLE	OHSR	20KL	Top slab , vertical connection	3.05
383	KUPPAM	SANTHIPURAM	GUNJANALAPALLI	CHINTHAKAMPALLE	OHSR	20KL	Top slab , vertical connection	3.1
384	KUPPAM	SANTHIPURAM	CHENGUBALLA	SETTIBALLA	OHSR	20KL	Top slab , vertical connection	3.04
385	KUPPAM	SANTHIPURAM	CHENGUBALLA	CHENGUBALLA	OHSR	20KL	Top slab , vertical connection	3.06
386	KUPPAM	SANTHIPURAM	CHENGUBALLA	SIVAKURABURU	OHSR	20KL	Top slab , vertical connection	3.08
387	KUPPAM	SANTHIPURAM	KENAMKULAPALLI	VENKATAPALLE	OHSR	20KL	Top slab , vertical connection	3.1
388	KUPPAM	SANTHIPURAM	CHENGUBALLA	SOGADABALLA	OHSR	20KL	Top slab , vertical connection	3.04
389	KUPPAM	SANTHIPURAM	REGADADINNEPALLE	CHINAGANDLAPALLE	OHSR	20KL	Top slab , vertical connection	3.06
390	KUPPAM	SANTHIPURAM	MULLURU	M.KRISHNAPURAM	OHSR	20KL	Top slab , vertical connection	3.08
391	KUPPAM	SANTHIPURAM	MULLURU	MULLURU	OHSR	20KL	Top slab , vertical connection	3.05
392	KUPPAM	SANTHIPURAM	KENAMKULAPALLI	BOYANAPALLE	OHSR	20KL	Top slab , vertical connection	5.85
393	KUPPAM	SANTHIPURAM	KENAMKULAPALLI	SIDDAVOORU	OHSR	20KL	Top slab , vertical connection	3.04
394	KUPPAM	SANTHIPURAM	SONNEGANIPALLE	GUNDUSETTIPALLE	OHSR	20KL	Top slab , vertical connection	3.08
395	KUPPAM	SANTHIPURAM	MATAM	MATAM	OHSR	20KL	Top slab , vertical connection	3.05
396	KUPPAM	SANTHIPURAM	MATAM	GANGATHIMMANAPALLE	OHSR	20KL	Top slab , vertical connection	3.1
397	KUPPAM	SANTHIPURAM	MATAM	PONNEPALLE	OHSR	20KL	Top slab , vertical connection	3.06

398	KUPPAM	SANTHIPURAM	MATAM	MATAMSANTHAMPALLE	OHSR	20KL	Top slab , vertical connection	3.08
399	KUPPAM	SANTHIPURAM	KENAMKULAPALLI	KENAMAKULAPALLE	OHSR	20KL	Top slab , vertical connection	3.05
400	KUPPAM	SANTHIPURAM	KENAMKULAPALLI	BADUGUMAKULAPALLE	OHSR	20KL	Top slab , vertical connection	3.1
401	KUPPAM	SANTHIPURAM	KENAMKULAPALLI	GADDURU	OHSR	20KL	Top slab , vertical connection	3.04
402	KUPPAM	SANTHIPURAM	KENAMKULAPALLI	EDDULAPALLE	OHSR	20KL	Top slab , vertical connection	3.06
403	KUPPAM	SANTHIPURAM	GUNJANALAPALLI	GUNJARLAPALLE	OHSR	20KL	Top slab , vertical connection	3.08
404	KUPPAM	SANTHIPURAM	GUNJANALAPALLI	NAKKANAPALLE	OHSR	20KL	Top slab , vertical connection	3.05
405	KUPPAM	SANTHIPURAM	RALLABADUGURU	RALLABADUGURU	OHSR	20KL	Top slab , vertical connection	8.42
406	KUPPAM	SANTHIPURAM	RALLABADUGURU	BANDATHIMMANAPALLE	OHSR	20KL	Top slab , vertical connection	3.06
407	KUPPAM	SANTHIPURAM	RALLABADUGURU	SETTIGARIKURABURU	OHSR	20KL	Top slab , vertical connection	3.08
408	KUPPAM	SANTHIPURAM	RALLABADUGURU	RAMAGARIPALLE	OHSR	20KL	Top slab , vertical connection	3.05
409	KUPPAM	SANTHIPURAM	RALLABADUGURU	GOLLAPALLE	OHSR	20KL	Top slab , vertical connection	3.04
410	KUPPAM	SANTHIPURAM	64 PEDDURU	GESIKAPALLE	OHSR	20KL	Top slab , vertical connection	3.08
411	KUPPAM	SANTHIPURAM	64 PEDDURU	SOLISETTIPALLE	OHSR	20KL	Top slab , vertical connection	3.05
412	KUPPAM	SANTHIPURAM	64 PEDDURU	SOMAPURAM	OHSR	20KL	Top slab , vertical connection	3.1
413	KUPPAM	SANTHIPURAM	64 PEDDURU	KARUMATLA	OHSR	20KL	Top slab , vertical connection	3.04
414	KUPPAM	SANTHIPURAM	C. BANDAPALLE	DOMMARATHIPPANAPALLE	OHSR	20KL	Top slab , vertical connection	3.06
415	KUPPAM	SANTHIPURAM	C. BANDAPALLE	MUDDANAPALLE	OHSR	20KL	Top slab , vertical connection	3.08
416	KUPPAM	SANTHIPURAM	64 PEDDURU	64 PEDDURU	OHSR	20KL	Top slab , vertical connection	3.05
417	KUPPAM	SANTHIPURAM	C. BANDAPALLE	BEVANAPALLE	OHSR	20KL	Top slab , vertical connection	3.04
418	KUPPAM	SANTHIPURAM	C. BANDAPALLE	C.BANDAPALLE	OHSR	20KL	Top slab , vertical connection	3.06
419	KUPPAM	SANTHIPURAM	C. BANDAPALLE	CHINNURU	OHSR	20KL	Top slab , vertical connection	3.05
420	KUPPAM	SANTHIPURAM	KARLAGATTA	CHEEMANAPALLE	OHSR	20KL	Top slab , vertical connection	3.1
421	KUPPAM	SANTHIPURAM	KARLAGATTA	VENKATAPURAM	OHSR	20KL	Top slab , vertical connection	3.04
422	KUPPAM	SANTHIPURAM	KARLAGATTA	KARLAGATTA	OHSR	20KL	Top slab , vertical connection	3.06
423	KUPPAM	SANTHIPURAM	MORASANAPALLI	JALLIGANIPALLE	OHSR	20KL	Top slab , vertical	3.08

							connection	
424	KUPPAM	SANTHIPURAM	MORASANAPALLI	NARSIMHAPALLE	OHSR	20KL	Top slab , vertical connection	3.05
425	KUPPAM	SANTHIPURAM	MORASANAPALLI	PAKAMPALLE	OHSR	20KL	Top slab , vertical connection	3.04
426	KUPPAM	SANTHIPURAM	MADAM PALLE	NADIMPALLE	OHSR	20KL	Top slab , vertical connection	3.08
427	KUPPAM	SANTHIPURAM	THUMISI	DONKUMANI PALLE	OHSR	20KL	Top slab , vertical connection	3.05
428	KUPPAM	SANTHIPURAM	ABAKALADODDI	ABAKALADODDI	OHSR	20KL	Top slab , vertical connection	3.04
429	KUPPAM	SANTHIPURAM	GUNJANALAPALLI	KARAGOWNURU	OHSR	20KL	Top slab , vertical connection	3.06
430	KUPPAM	SANTHIPURAM	ABAKALADODDI	KOTHIGUTTAPALLE	OHSR	20KL	Top slab , vertical connection	3.08
431	KUPPAM	SANTHIPURAM	GUNJANALAPALLI	THUMMISIKOTHURU	OHSR	20KL	Top slab , vertical connection	3.05
432	KUPPAM	SANTHIPURAM	ABAKALADODDI	KAKARLAVANKA	OHSR	20KL	Top slab , vertical connection	3.1
433	KUPPAM	SANTHIPURAM	GUNJANALAPALLI	PEDDABOMMANAPALLE	OHSR	20KL	Top slab , vertical connection	3.04
434	KUPPAM	SANTHIPURAM	ABAKALADODDI	VENKATESHPURAM	OHSR	20KL	Top slab , vertical connection	3.06
435	KUPPAM	SANTHIPURAM	ABAKALADODDI	GANAGAPURAM	OHSR	20KL	Top slab , vertical connection	3.08
436	KUPPAM	SANTHIPURAM	KENAMKULAPALLI	ARIMUTHANAPALLE	OHSR	20KL	Top slab , vertical connection	3.1
437	KUPPAM	SANTHIPURAM	KENAMKULAPALLI	SANTHIPURAM	OHSR	20KL	Top slab , vertical connection	5.73
438	KUPPAM	SANTHIPURAM	DANDIKUPPAM	NALLARALLAPALLE	OHSR	20KL	Top slab , vertical connection	3.06
439	KUPPAM	SANTHIPURAM	DANDIKUPPAM	DANDIKUPPAM	OHSR	20KL	Top slab , vertical connection	5.81
440	KUPPAM	SANTHIPURAM	DANDIKUPPAM	SIDDAREDDIPALLE	OHSR	20KL	Top slab , vertical connection	3.05
441	KUPPAM	SANTHIPURAM	DANDIKUPPAM	INDIRANAGAR	OHSR	20KL	Top slab , vertical connection	3.04
442	KUPPAM	SANTHIPURAM	SONNEGANIPALLE	30 SONNEGOWNIPALLE	OHSR	20KL	Top slab , vertical connection	3.08
443	KUPPAM	SANTHIPURAM	MATAM	KODITHIPALLEMITTA	OHSR	20KL	Top slab , vertical connection	3.05
444	KUPPAM	SANTHIPURAM	SONNEGANIPALLE	KUTHEGANIPALLE	OHSR	20KL	Top slab , vertical connection	3.1
445	KUPPAM	SANTHIPURAM	SONNEGANIPALLE	NAYANAPALLE	OHSR	20KL	Top slab , vertical connection	3.04
446	KUPPAM	SANTHIPURAM	MATAM	VENKATESUPURAM	OHSR	20KL	Top slab , vertical connection	3.06
447	KUPPAM	SANTHIPURAM	MATAM	SANTHURU	OHSR	20KL	Top slab , vertical connection	3.08
448	KUPPAM	SANTHIPURAM	KOLAMADUGU	VETAGIRIKOTHUR	OHSR	20KL	Top slab , vertical connection	3.04

449	KUPPAM	SANTHIPURAM	KOLAMADUGU	ODDUMADI	OHSR	20KL	Top slab , vertical connection	3.06
450	KUPPAM	SANTHIPURAM	DANDIKUPPAM	CHOWDAMPALLE	OHSR	20KL	Top slab , vertical connection	3.08
451	KUPPAM	SANTHIPURAM	KOLAMADUGU	KADIRIMUTHAMAPALLE	OHSR	20KL	Top slab , vertical connection	3.05
452	KUPPAM	SANTHIPURAM	KOLAMADUGU	REDLAPALLE	OHSR	20KL	Top slab , vertical connection	3.1
453	KUPPAM	SANTHIPURAM	ABAKALADODDI	VEDURUGUTTAPALLE	OHSR	20KL	Top slab , vertical connection	3.04
454	KUPPAM	SANTHIPURAM	ABAKALADODDI	JANGALAPALLE	OHSR	20KL	Top slab , vertical connection	3.06
455	KUPPAM	SANTHIPURAM	THUMISI	THUMMISI	OHSR	20KL	Top slab , vertical connection	3.08
456	KUPPAM	SANTHIPURAM	THUMISI	THULASINAYANIPALLE	OHSR	20KL	Top slab , vertical connection	3.1
457	KUPPAM	SANTHIPURAM	MORASANAPALLI	KANAMALADODDI	OHSR	20KL	Top slab , vertical connection	3.04
458	KUPPAM	SANTHIPURAM	KADAPALLE	KADAPALLE	OHSR	20KL	Top slab , vertical connection	3.06
459	KUPPAM	SANTHIPURAM	KADAPALLE	KALIGANURU	OHSR	20KL	Top slab , vertical connection	3.08
460	KUPPAM	SANTHIPURAM	KADAPALLE	SILAMAKULARAI	OHSR	20KL	Top slab , vertical connection	3.05
461	KUPPAM	SANTHIPURAM	KADAPALLE	PODUCHENLU	OHSR	20KL	Top slab , vertical connection	3.1
462	KUPPAM	SANTHIPURAM	KARLAGATTA	THAMBIGANIPALLE	OHSR	20KL	Top slab , vertical connection	3.04
463	KUPPAM	SANTHIPURAM	KARLAGATTA	PREETHICHAMANURU	OHSR	20KL	Top slab , vertical connection	3.06
464	KUPPAM	SANTHIPURAM	KADAPALLE	PODURU	OHSR	20KL	Top slab , vertical connection	3.05
465	KUPPAM	SANTHIPURAM	KADAPALLE	MADANAPALLE	OHSR	20KL	Top slab , vertical connection	3.1
466	KUPPAM	SANTHIPURAM	KADAPALLE	BANTHIMADUGUGOLLAPALLE	OHSR	20KL	Top slab , vertical connection	3.06
467	KUPPAM	SANTHIPURAM	KADAPALLE	THIMMARAJUPALLE	OHSR	20KL	Top slab , vertical connection	3.08
468	KUPPAM	SANTHIPURAM	KADAPALLE	SOMARAJUPURAM	OHSR	20KL	Top slab , vertical connection	3.05
469	KUPPAM	SANTHIPURAM	KADAPALLE	KADIRIOBANAPALLE	OHSR	20KL	Top slab , vertical connection	3.1
470	KUPPAM	SANTHIPURAM	KOLAMADUGU	JEEDIMANIPALLE	OHSR	20KL	Top slab , vertical connection	3.06
471	KUPPAM	SANTHIPURAM	KOLAMADUGU	CHILLAMANIPALLE	OHSR	20KL	Top slab , vertical connection	3.08
472	KUPPAM	SANTHIPURAM	KOLAMADUGU	KOLAMADUGU	OHSR	20KL	Top slab , vertical connection	3.1
473	KUPPAM	SANTHIPURAM	KOLAMADUGU	AMMAVARIPETA	OHSR	20KL	Top slab , vertical connection	3.04
474	KUPPAM	SANTHIPURAM	KOLAMADUGU	RAMAPURAM	OHSR	20KL	Top slab , vertical	3.06

							connection	
475	KUPPAM	SANTHIPURAM	SIVARAMPURAM	SANTHAMPALLE	OHSR	20KL	Top slab , vertical connection	3.08
476	KUPPAM	SANTHIPURAM	SIVARAMPURAM	SIVARAMAPURAM	OHSR	20KL	Top slab , vertical connection	3.1
477	KUPPAM	SANTHIPURAM	SIVARAMPURAM	GATTURU	OHSR	20KL	Top slab , vertical connection	3.04
478	KUPPAM	SANTHIPURAM	SIVARAMPURAM	NANJAMPETA	OHSR	20KL	Top slab , vertical connection	3.06
479	KUPPAM	SANTHIPURAM	SIVARAMPURAM	KOTAGADDA	OHSR	20KL	Top slab , vertical connection	3.08
480	KUPPAM	SANTHIPURAM	SIVARAMPURAM	VODDUVANKA	OHSR	20KL	Top slab , vertical connection	3.1
481	KUPPAM	SANTHIPURAM	CHINNARADODDI	KOTHAPETA	OHSR	20KL	Top slab , vertical connection	3.06
482	KUPPAM	SANTHIPURAM	CHINNARADODDI	S.GOLLAPALLE	OHSR	20KL	Top slab , vertical connection	3.08
483	KUPPAM	SANTHIPURAM	CHINNARADODDI	KONDATHIMMANAPALLE	OHSR	20KL	Top slab , vertical connection	3.05
484	KUPPAM	SANTHIPURAM	KARLAGATTA	CHINNA KARALAGATTA	OHSR	20KL	Top slab , vertical connection	3.08
485	G.D Nellore	G.D Nellore	Kadapagunta	Kadapagunta H.W	OHSR	20 KL	Ateel exposed in Columns, Braces and Top slab	2.00
486	G.D Nellore	G.D Nellore	Kalijavedu	K.Nasampalli	OHSR	20 KL	Heavy Leakage in side walls & Bottom	1.50
487	G.D Nellore	G.D Nellore	Vepanjeri	Jangalaplli	OHSR	20 KL	Ateel exposed in Columns, Braces and Top slab	2.00
488	G.D Nellore	G.D Nellore	Ambodarapalli	Edharapalem	OHSR	20 KL	Ateel exposed in Columns, Braces and Top slab	2.00
489	G.D Nellore	G.D Nellore	Vinjam	Vinjam H.W	OHSR	20 KL	Ateel exposed in Columns, Braces and Top slab	2.00
490	Palamaner	V.Kota	Bairupalle	Madakuppam	OHSR	20	Top slab damaged	3.00
491	Palamaner	V.Kota	Bodiguttapalle	Chadepalle	OHSR	20	Sidewall damaged	3.50
492	Palamaner	V.Kota	Bodiguttapalle	Yerrampalle	OHSR	20	Top slab damaged	3.50
493	Palamaner	V.Kota	Boyachinnaganapalle	Bommanapalle	OHSR	20	Sidewall damaged	4.00
494	Palamaner	V.Kota	Boyachinnaganapalle	Nayakaneri	OHSR	20	Top slab damaged	3.00
495	Palamaner	V.Kota	Gonumakulapalle	Chinnasyama	OHSR	20	Sidewall damaged	5.00
496	Palamaner	V.Kota	Gonumakulapalle	Nagireddypalle	OHSR	20	Top slab damaged	2.00
497	Palamaner	V.Kota	Jounipalle	Nakkanapalle	OHSR	20	Sidewall damaged	1.50
498	Palamaner	V.Kota	Jounipalle	Eguvapalle	OHSR	20	Top slab damaged	2.00
499	Palamaner	V.Kota	Kongatam	Gandaramakulapalle	OHSR	20	Sidewall damaged	2.00
500	Palamaner	V.Kota	Krishnapuram	Motlapalle	OHSR	20	Top slab damaged	2.00
501	Palamaner	V.Kota	Krishnapuram	Danamaiahgaripalle	OHSR	20	Sidewall damaged	3.00
502	Palamaner	V.Kota	Yalakallu	Thimmarajap	OHSR	20	Top slab	3.00

				uram			damaged	
503	Palamaner	V.Kota	Yalakallu	Kp Banda	OHSR	20	Sidewall damaged	3.00
504	Palamaner	V.Kota	Yalakallu	Yerrinagepalle	OHSR	20	Top slab damaged	2.50
505	PALAMANER	BAIREDDI PALLE	ALAPALLI	ALAPALLE	OHSR	20	Sidewall damaged	2.50
506	PALAMANER	BAIREDDI PALLE	ALAPALLI	MUGANAPALLE	OHSR	20	Top slab damaged	3.50
507	PALAMANER	BAIREDDI PALLE	ALAPALLI	NANCHAKUPPAM	OHSR	20	Sidewall damaged	3.10
508	PALAMANER	BAIREDDI PALLE	BAIREDDIPALLI	BAIREDDIPALLE	OHSR	20	Top slab damaged	8.00
509	PALAMANER	BAIREDDI PALLE	BELUPALLI	AKULAKOTHUR	OHSR	20	Sidewall damaged	3.50
510	PALAMANER	BAIREDDI PALLE	BELUPALLI	BELLAMMADUGU	OHSR	20	Top slab damaged	3.10
511	PALAMANER	BAIREDDI PALLE	BELUPALLI	BELUPALLE	OHSR	20	Sidewall damaged	2.50
512	PALAMANER	BAIREDDI PALLE	BELUPALLI	BURISETTIPALLE	OHSR	20	Top slab damaged	3.60
513	PALAMANER	BAIREDDI PALLE	BELUPALLI	CHIKKANAPALLE	OHSR	20	Sidewall damaged	2.10
514	PALAMANER	BAIREDDI PALLE	BELUPALLI	PATHAPALLE	OHSR	20	Top slab damaged	2.80
515	PALAMANER	BAIREDDI PALLE	CHAPPIDIPALLI	CHAPPIDIPALLE	OHSR	20	Sidewall damaged	2.90
516	PALAMANER	BAIREDDI PALLE	CHAPPIDIPALLI	JANGALA AGRAHARAM	OHSR	20	Top slab damaged	3.50
517	PALAMANER	BAIREDDI PALLE	CHAPPIDIPALLI	VIRUPAKSHAPURAM	OHSR	20	Sidewall damaged	2.20
518	PALAMANER	BAIREDDI PALLE	DEVADODDI	DEVADODDI	OHSR	20	Top slab damaged	3.20
519	PALAMANER	BAIREDDI PALLE	DEVADODDI	GUNTAKURRAPALLE	OHSR	20	Sidewall damaged	3.50
520	PALAMANER	BAIREDDI PALLE	DEVADODDI	KAMINAYANIPALLE	OHSR	20	Top slab damaged	3.00
521	PALAMANER	BAIREDDI PALLE	DHARMAPURI	DHARMAPURE	OHSR	20	Sidewall damaged	2.50
522	PALAMANER	BAIREDDI PALLE	DHARMAPURI	MEKALANAGIREDDIPALLE	OHSR	20	Top slab damaged	2.40
523	PALAMANER	BAIREDDI PALLE	DHARMAPURI	MULATHIMMEPALLE	OHSR	20	Sidewall damaged	2.90
524	PALAMANER	BAIREDDI PALLE	DHARMAPURI	THOORPUGADDA	OHSR	20	Top slab damaged	3.00
525	PALAMANER	BAIREDDI PALLE	GADDUR	GADDUR	OHSR	20	Sidewall damaged	3.05
526	PALAMANER	BAIREDDI PALLE	GADDUR	KOTREPALLE	OHSR	20	Top slab damaged	3.20
527	PALAMANER	BAIREDDI PALLE	GANGINAYANIPALLI	GANGINAYANIPALLE	OHSR	20	Sidewall damaged	3.60
528	PALAMANER	BAIREDDI PALLE	GOLLACHEMANAPALLE	MURARIPALLE	OHSR	20	Top slab damaged	3.00
529	PALAMANER	BAIREDDI PALLE	GOLLACHEMANAPALLE	THAVADAKUPPAM	OHSR	20	Sidewall damaged	3.20
530	PALAMANER	BAIREDDI PALLE	GOLLACHEMANAPALLE	YETIGDDINDLU	OHSR	20	Top slab damaged	3.50

531	PALAMANER	BAIREDDI PALLE	KAMBAMPALLI	DASARALAPALLE	OHSR	20	Sidewall damaged	3.20
532	PALAMANER	BAIREDDI PALLE	KAMBAMPALLI	JAMBUGUNDLAPALLE	OHSR	20	Top slab damaged	3.10
533	PALAMANER	BAIREDDI PALLE	KAMBAMPALLI	RAMAPURAM	OHSR	20	Sidewall damaged	3.50
534	PALAMANER	BAIREDDI PALLE	KAMMANAPALLE	JALARIPALLE	OHSR	20	Top slab damaged	2.80
535	PALAMANER	BAIREDDI PALLE	KAMMANAPALLE	KAMMANAPALLE	OHSR	20	Sidewall damaged	2.90
536	PALAMANER	BAIREDDI PALLE	KOTHUR	KOTHUR	OHSR	20	Top slab damaged	3.20
537	PALAMANER	BAIREDDI PALLE	KOTHUR	RAMASAMUDRAM	OHSR	20	Sidewall damaged	3.40
538	PALAMANER	BAIREDDI PALLE	LAKKANAPALLI	LAKKANAPALLE	OHSR	20	Top slab damaged	4.10
539	PALAMANER	BAIREDDI PALLE	LAKKANAPALLI	PEDDAPURAM	OHSR	20	Sidewall damaged	1.90
540	PALAMANER	BAIREDDI PALLE	LAKKANAPALLI	SETTIPALLE	OHSR	20	Top slab damaged	2.50
541	PALAMANER	BAIREDDI PALLE	NELLIPATLA	BAPALAVATHAM	OHSR	20	Sidewall damaged	2.90
542	PALAMANER	BAIREDDI PALLE	NELLIPATLA	NELLIPATLA I	OHSR	20	Top slab damaged	3.60
543	PALAMANER	BAIREDDI PALLE	PATHAPETA	KUPPANAPALLE	OHSR	20	Sidewall damaged	3.10
544	PALAMANER	BAIREDDI PALLE	PATHAPETA	PATHAPETA	OHSR	20	Top slab damaged	3.50
545	PALAMANER	BAIREDDI PALLE	PATHURNATHAM	MITTAKURAPALLI	OHSR	20	Sidewall damaged	3.00
546	PALAMANER	BAIREDDI PALLE	PATHURNATHAM	PATHURNATHAM	OHSR	20	Top slab damaged	3.10
547	PALAMANER	BAIREDDI PALLE	PEDDACHILLARIKUNTA	PEDDACHELLARAGUNTA	OHSR	20	Sidewall damaged	3.60
548	PALAMANER	BAIREDDI PALLE	THEERTHAM	KAIGALLU	OHSR	20	Top slab damaged	2.90
549	PALAMANER	BAIREDDI PALLE	THEERTHAM	THEERTHAM	OHSR	20	Sidewall damaged	3.20
550	PALAMANER	BAIREDDI PALLE	VENGAMVARIPALLE	KADATHATTAPALLE	OHSR	20	Top slab damaged	2.50
551	PALAMANER	BAIREDDI PALLE	VENGAMVARIPALLE	VENGAMVARIPALLE	OHSR	20	Sidewall damaged	2.40
552	Madanapalle	Madanapalle	Penchupadu	Gollapalle	OHSR	20	Walls leakage and present working condition.	1.50
553	Madanapalle	Madanapalle	Penchupadu	Kattubavi	OHSR	20	Walls leakage and present working condition.	1.50
554	Madanapalle	Madanapalle	Kondamarripalle	Bodumaladinne	OHSR	20	Walls leakage and present working condition.	1.50
555	Madanapalle	Madanapalle	Kollabylu	Indiramma Colony	OHSR	20	Walls leakage and present working condition.	2.00
556	Thamballapalle	B.Kothakota	B.Kothakota	B.Kothakota	OHSR	20	Walls leakage and present working condition.	1.50

557	Thamballapalle	B.Kothakota	Gummsamudram	Buchireddigaripalle	OHSR	20	Top slab damaged, and present working condition.	1.00
558	Thamballapalle	B.Kothakota	Gollapalle	Gollapalle Hw	OHSR	20	Top slab damaged, and present working condition.	1.00
559	Thamballapalle	B.Kothakota	Thummanagutta	Kanikala Thopu	OHSR	20	Walls leakage and present working condition.	1.00
560	Thamballapalle	B.Kothakota	Beerangi	Beerangi	OHSR	20	Walls leakage and present working condition.	1.00
561	Thamballapalle	B.Kothakota	Beerangi	Gudipalle	OHSR	20	Top slab damaged, and present working condition.	1.00
562	Thamballapalle	Thamballapalle	ZUNJURAPENTA	KAMMALAVANDLAPALLE	OHSR	20	Walls leakage and present working condition.	2.00
563	Thamballapalle	Thamballapalle	REDDIKOTA	REDDIKOTA	OHSR	20	Top slab damaged, and present working condotion.	2.00
564	Thamballapalle	Thamballapalle	EDDULAVARIPALLE	DIGUVAGALIGUTTAPALLE	OHSR	20	Walls leakage and present working condition.	1.00
565	Thamballapalle	Thamballapalle	RENUMAKULAPALLE	JOGIVANIBURUJU	OHSR	20	Top slab damaged, and present working condition.	1.00
566	Thamballapalle	Peddamandyam	Bandameedapalle	Tussuvaripalle	OHSR	20	Walls leakage and present working condition.	2.00
567	Piler	Piler	Mellacheruvu	Madigapalli	OHSR	20	Plasterings	2.00
568	Piler	K.V.Palli	KV Palle	Theetaguntapalle	GLSR	20	Top slab damaged, and present working condition.	2.00
569	Piler	K.V.Palli	K.V.Palli	Kondareddygari palle	GLSR	20	Walls leakage and present working condition.	2.00
570	Piler	K.V.Palli	K.V.Palli	Zillellamanda	GLSR	20	Top slab damaged, and present working condition.	2.00
571	Piler	Kalakada	Kalakada	Diguvathanda	GLSR	20	Top slab damaged, and present working condition.	2.00
572	Chandragiri	C.G.gallu	C.G.gallu	C.G.gallu	OHSR	40	Columns, spair stair case and plastering, Working	5.00
573	Chandragiri	C.G.gallu	Deendarlapalli	THAVVAVANDLAPALLE	OHSR	20	spair stair case and plastering, Working	2.50
574	Chandragiri	C.G.gallu	Yegavuru	Parimalavandlapalli	OHSR	20	Columns, spair stair case and	3.00

							plastering, Working	
575	Chandragiri	C.G.gallu	C.G.gallu	Rajuvaripalli	OHSR	20	Columns, spair stair case and plastering, Working	3.50
576	Chandragiri	C.G.gallu	CHITTECHERLA	Thummachenupalli	OHSR	20	Columns, spair stair case and plastering, Working	3.50
577	Chandragiri	C.G.gallu	Thippireddygaripalli	Thippireddygaripalli	OHSR	20	spair stair case and plastering, Working	2.50
578	Chandragiri	C.G.gallu	Rangannagarigadda	Peddapalli	OHSR	20	spair stair case and plastering, Working	3.00
579	Chandragiri	C.G.gallu	Chittecherla	BHUTAMVARIPALLE	OHSR	20	spair stair case and plastering, Working	2.50
580	Chandragiri	C.G.gallu	Digavoor	Santhi nagar	OHSR	20	spair stair case and plastering, Working	2.00
581	Chandragiri	C.G.gallu	Chattevaripalem	Kataruvandlapalli M/W	OHSR	20	Columns, spair stair case and plastering, Working	4.00
582	Chandragiri	YV Palem	YERRAVARIPALEM	SWARNAVARIPALLE	OHSR	20	Columns, spair stair case and plastering, Working	4.00
583	Chandragiri	YV Palem	Chinthagunta	Chinthagunta Kasba	OHSR	20	Columns, spair stair case and plastering, Working	4.00
584	Chandragiri	YV Palem	Ustikayalapenta	Penukondavaripalli	OHSR	20	spair stair case and plastering, Working	2.00
585	Chandragiri	YV Palem	Y.V. Palem	Y.V. Palem	OHSR	20	spair stair case and plastering, Working	2.00
586	Chandragiri	YV Palem	Kammalayyagaripalli	Bodduvandlapalli	OHSR	20	spair stair case and plastering, Working	2.00
587	Chandragiri	YV Palem	Nerabylu	Bijjepalli	OHSR	20	spair stair case and plastering, Working	2.00
588	Chandragiri	YV Palem	Bodevandlapalli	Bodevandlapalli	OHSR	20	Columns, spair stair case and plastering, Working	5.00
589	Chandragiri	YV Palem	V R Agraharam	V R Agraharam	OHSR	20	Columns, spair stair case and plastering, Working	4.00
590	Chandragiri	YV Palem	V R Agraharam	Nadimpalli	OHSR	20	spair stair case and plastering, Working	2.00
591	Chandragiri	Pakala	Peddaramapuram	Venkatramapuram	OHSR	20	Columns, spair stair case and plastering,	4.00

							Working	
592	Chandragiri	Pakala	Pantapalli	Jayadevapuram	OHSR	20	Columns, spair stair case and plastering, Working	4.00
593	Chandragiri	Pakala	Mogarala	Thurupupalli	OHSR	20	spair stair case and plastering, Working	2.00
594	Chandragiri	Pakala	Damalacheruvu	KUKKALAPALLE	OHSR	20	spair stair case and plastering, Working	1.00
595	Sathyavedu	Narayanavanam	VK palem	Nagileru	OHSR	40	Top slab, Verticals, Plastering to braces, Ladder and columns repair, working	5.00
596	Sathyavedu	Narayanavanam	Palamangalam (South)	Palamangalam South	OHSR	40	Top slab, Verticals, Plastering to braces, Ladder and columns repair, working	5.00
597	Sathyavedu	Pichatur	Neeruvoi	Neeruvoi Koth HW	OHSR	20	Top slab, Verticals, Plastering to braces, Ladder and columns repair, working	4.00
598	Sathyavedu	Pichatur	Neeruvoi	Neeruvoi BC Colony	OHSR	20	Top slab, Verticals, Plastering to braces, Ladder and columns repair, working	4.00
599	Sathyavedu	Pichatur	Velluru	Velluru Kotha HW	OHSR	20	Top slab, Verticals, Plastering to braces, Ladder and columns repair, working	4.00
600	Sathyavedu	KVB Puram	Olluru	Olluru	OHSR	20	Top slab, Verticals, Plastering to braces, Ladder and columns repair, working	4.00
601	Nagari	Nagari	M Kothuru	M Kothuru	OHSR	40	Top slab, plastering, Ladders, vertical connections	5.00
602	Nagari	Nagari	VNR Peta	VNR Peta	OHSR	20	Top slab, plastering, Ladders, vertical connections	5.00
603	Nagari	Nagari	Adivikothuru	Adivikothuru	OHSR	40	Top slab, plastering, Ladders, vertical	5.00

							connections	
604	Nagari	Nagari	Nambakam	Agaram	OHSR	20	Top slab, plastering, Ladders, vertical connections	5.00
605	Nagari	Nagari	Bugga Agraharam	Bugga Agraharam	OHSR	20	Top slab, plastering, Ladders, vertical connections	5.00
606	Nagari	Nagari	Beerakuppam	Beerakuppam	OHSR	40	plastering, Ladders, vertical connections	5.00
607	Nagari	Nagari	Nambakam	Namabakam	OHSR	20	plastering, Ladders, vertical connections	4.00
608	Nagari	Nagari	Inambakam	Inambakam HW	OHSR	20	plastering, Ladders, vertical connections	3.00
609	Nagari	Nindra	Elakaturu	Elakaturu	OHSR	20	Top slab, plastering, Ladders, working	2.00
610	Nagari	Nindra	Kaipakam	Kaipakam	OHSR	20	Top slab, plastering, Ladders, working	2.00
611	Nagari	Nindra	Netteri	Netteri YC	OHSR	20	Top slab, plastering, Ladders, working	2.00
612	Nagari	Nindra	Netteri	Netteri	OHSR	20	Top slab, plastering, Ladders, working	2.00
613	Nagari	Nindra	Athuru	Mangalagiri kandriga HW	OHSR	20	Top slab, plastering, Ladders, working	2.00
614	Nagari	Nindra	Ororupeta	Orupeta HW	OHSR	20	vertical connections, working	1.00
615	Nagari	Nindra	Nindra	Nindra YC	OHSR	20	Top slab, plastering, Ladders, working	2.00
616	Nagari	Nindra	G.N.Kandriga	G.N.Kandriga	OHSR	20	vertical connections, working	1.00
617	Nagari	Puttur	Parameswara mangalam	Parameswara mangalam	OHSR	20	Plastering, Vertical connections, working	2.00
618	Nagari	Puttur	Taduku	CH.NAIDU KANDRIGA	OHSR	20	Plastering, Vertical connections, working	2.00
619	Nagari	Puttur	KBR Puram	KBR Puram AAW	OHSR	20	Top slab, plastering, vertical connections	3.00
620	Nagari	Puttur	KBR Puram	KBR Puram	OHSR	60	Top slab, plastering, Ladders, vertical connections	5.00
621	Nagari	Vadamala peta	CHINTHAKALVA	CHINTHAKALVA	OHSR	20	Top slab, plastering, Ladders, vertical connections	4.00

622	Nagari	Vadamala peta	Sitaramapura m	Sitaramapura m	OHSR	40	Top slab, plastering, Ladders, vertical connections	5.00
623	Nagari	Vadamala peta	Pathiputtur	Pathiputtur	OHSR	40	Top slab, plastering, Ladders, vertical connections	5.00
624	Nagari	Vadamala peta	Pathiputtur	Pachikalva	OHSR	40	Ladders, vertical connections	2.00
625	Nagari	Vadamala peta	Narayanapura m	Narayanapura m	OHSR	20	Top slab, plastering, Ladders, vertical connections	5.00
626	Nagari	Vadamala peta	AM Puram	AM Puram	OHSR	20	Top slab, plastering, Ladders, vertical connections	5.00
627	Nagari	Vadamala peta	Vadamalapeta	Vadamalapeta	OHSR	60	Top slab, plastering, Ladders, vertical connections	5.00
628	Nagari	Vadamala peta	Narayanapura m	Narayanapura m AAW	GLSR	20	Plastering, Connections	4.00
629	Nagari	Vadamala peta	TC Agraharam	TC Agraharam	OHSR	40	Ladders, vertical connections	2.00
630	Nagari	Vadamala peta	Padiredu	Padiredu	OHSR	40	Ladders, vertical connections	2.00
631	Nagari	Vadamala peta	Kayam	Kayam	OHSR	40	Ladders, vertical connections	2.00
632	Nagari	Vadamala peta	Balinaidukand riga	NVR Kandriga HW	OHSR	20	Top slab, plastering, Ladders, vertical connections	5.00
633	Nagari	Vadamala peta	Balinaidukand riga	Balinaidukand riga	OHSR	20	Top slab, plastering, Ladders, vertical connections	4.00
634	Nagari	Vijayapura m	Mangalam	Muthayalredd y kandriga	OHSR	20	Top slab, plastering, Ladders, vertical connections	5.00
635	Nagari	Vijayapura m	Pannur	Pannur	OHSR	60	Top slab, plastering, Ladders, vertical connections	5.00
636	Nagari	Vijayapura m	Jaganadhapur am	Krishansamud ram	OHSR	20	Ladders, vertical connections	2.00
637	Nagari	Vijayapura m	Illathur	Illathur HW	OHSR	40	Top slab, plastering, Ladders, vertical connections	4.00
638	Nagari	Vijayapura m	Narapurajuka ndriaga	Narapurajuka ndriaga	OHSR	20	Top slab, plastering, Ladders, vertical connections	4.00
639	Nagari	Vijayapura m	Pathaarcot	Pathaarcot	OHSR	40	Top slab, plastering, Ladders, vertical connections	5.00

640	Nagari	Vijayapuram	Alapakam	Kammakandriga	OHSR	20	Ladders, vertical connections	2.00
641	Nagari	Vijayapuram	Buchivanatham	Istakameswarapuram	OHSR	20	Top slab, plastering, Ladders, vertical connections	4.00
642	Nagari	Vijayapuram	Buchivanatham	Buchivanatha HW	OHSR	20	Top slab, plastering, Ladders, vertical connections	4.00
643	Nagari	Vijayapuram	Mallareddykandriga	Mallareddykandriga	OHSR	40	Top slab, plastering, Ladders, vertical connections	4.00
644	Nagari	Vijayapuram	Sriharipuram	Sriharipuram AAW	OHSR	20	Ladders, vertical connections	2.00
645	Nagari	Vijayapuram	Sriharipuram	Lakshmivilasapuram	OHSR	20	Ladders, vertical connections	2.00
646	Nagari	Vijayapuram	Kosalanagaram	Kesavapuram AAW	GLSR	20	Top slab, side wall, connections	4.00
647	Nagari	Vijayapuram	Kosalanagaram	Kesavapuram	GLSR	20	Top slab, side wall, connections	4.00
648	Nagari	Vijayapuram	Vijayapuram	Dakshina MW	GLSR	20	Top slab, side wall, connections	3.00
649	Nagari	Vijayapuram	Kshurikapuram	Eguvamahaverapuram	GLSR	20	Top slab, side wall, connections	3.00
650	Nagari	Vijayapuram	K.V.Puram	Sreeramapuram	OHSR	40	Top slab, plastering, Ladders, vertical connections	5.00
651	Nagari	Vijayapuram	Kalikapuram	Kalikapuram BC	OHSR	20	Plastering, Ladders, vertical connections	4.00
652	Nagari	Vijayapuram	Kaliamabakam	Kaliamabakam HW	OHSR	40	Plastering, Ladders, vertical connections	3.00
653	Nagari	Vijayapuram	Kaliamabakam	Kaliamabakam	OHSR	20	Top slab, plastering, Ladders, vertical connections	5.00
654	Nagari	Vijayapuram	Pannuru	Pannuru HW	OHSR	40	Plastering, Ladders, vertical connections	3.00
655	Nagari	Vijayapuram	Vijayapuram	Vijayapuram HW	OHSR	20	Plastering, Ladders, vertical connections	2.00
656	Nagari	Vijayapuram	Gangamambapuram	Gangamambapuram	OHSR	20	Top slab, Plastering, Ladders, vertical connections	5.00
657	Srikalahasti	Thottambedu	Gundeligunta	Gundeligunta	OHSR	40	Top slab, Plastering, working	2.00
658	Srikalahasti	Thottambedu	Thottambedu	PATHAVOORU	OHSR	40	Vertical connection, working	1.50
659	Srikalahasti	Thottambedu	Kanchanapalli	Kanchanapalli	OHSR	20	Vertical connection, Ladder, working	1.50

660	Srikalahasti	Yerpedu	Madibaka	Madibaka	OHSR	20	Vertical connection, working	1.50
661	Srikalahasti	Yerpedu	Penumallam	Mittamidakhandriga	OHSR	40	Plastering, working	1.50
662	Srikalahasti	Yerpedu	Gudimallam	Gudimallam	OHSR	20	Plastering, working	1.50
663	Srikalahasti	Yerpedu	Penumallam	Penumallam	OHSR	20	Plastering, working	1.50
664	Srikalahasti	Yerpedu	Vikruthamalla	Vikruthamalla	OHSR	40	Plastering, working	2.00
665	Srikalahasti	Yerpedu	Jangalapalli	Jangalapalli	OHSR	20	Top slab, Plastering, working	2.00
666	Srikalahasti	Renigunta	THANDLAMANAGALAM	THANDLAM HARIJANAWADA	OHSR	20	Top slab repair, working	2.00
667	Srikalahasti	Renigunta	Guthivaripalli	Guthivaripalli	OHSR	40	Top slab repair, working	2.00
668	Srikalahasti	Srikalahasti	Erragudipadu	Erragudipadu	OHSR	40	Top slab repair, working	1.50
669	Srikalahasti	Srikalahasti	Uranduru	Uranduru	OHSR	40	Top slab repair, working	2.00
670	Sathyavedu	BN Kandriga	Peddapalaved u	Peddapalaved u	OHSR	40	Spair stair case and plastering, verticals, Working	4.00
671	Sathyavedu	BN Kandriga	P.V.Kandriga	R.G.Badava	OHSR	20	Plastering, verticals, Working	2.00
672	Sathyavedu	BN Kandriga	Neerpakota	Neerpakota YC	GLSR	60	Plastering, Connections	3.00
673	Sathyavedu	BN Kandriga	Kukkambaka m	Thanigallu	OHSR	20	Spair stair case and plastering, verticals, Working	4.80
674	Sathyavedu	BN Kandriga	Thalarivettu	Thalarivettu	OHSR	40	Spair stair case and plastering, verticals, Working	4.90
675	Sathyavedu	BN Kandriga	Kalivettu	kalivettu HW	OHSR	40	Spair stair case and plastering, verticals, Working	4.90
								1963.01

//FORWARDED BY ORDER//

SECTION OFFICER